


# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 01-08-2021		District: Sitamathi
Division : Beland		Length (km): 0.500
Name of the Road: L048 - PMHSY Road to Nandwagan South Tola		
Scheme/Programme: PMHSY		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:-		
2.	<b>Cross Drainage</b>	No culvert
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—
Observation Remarks:-		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:-		
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Name of Officer:- Rana Barun Kumar Singh  
 Designature:- Executive Engineer  
 RWD, Regional Laboratory Bhagalpur

Sub Division  
 (except Road Furniture)  
  
 01.08.2021  
 (Signature)