

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 29.07.2021 District: Motihari
 Division : Chakiya Length (km): 1.600
 Name of the Road: Kucina Bhumihar Tola Ganeswar Thakur Ke Ghar
 Scheme/Programme: To Prathmik Vidhyalay Kucina
 MMGSY (Gen)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	—

Observation Remarks:- PCC pavement found honeycombed

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U

Observation Remarks:- 200 M² stones not found

4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Unsatisfactory

Name of Officer:-

Pramod Kumar

Designature:-

EE, Reg. Lab., Sasaram

29/07/2021
(Signature)