

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक 1333 (अइ)/बाँका

दिनांक 01/08/2021

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बाँका-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
विहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय :-

शीर्ष "3054 एम0आर0" योजना अन्तर्गत आवंटन के संबंध में।

महाराज,

उपरोक्त विषयक से संबंधित एम0आर03054 योजना अन्तर्गत संवेदक द्वारा कराए
गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधिव्यधित राशि रुपये 1,40,40,000/-लाख का
आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु-1 अधियाचना प्रपत्र
2.IRI Report

विश्वसमान

02.08.21

कार्यपालक अभियंता

ग्रामोपवि0 कार्य प्रमण्डल,

बाँका-2

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक...../बाँका

दिनांक

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बाँका-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय :- शीर्ष "3054 एम0आर0" योजना अन्तर्गत आवंटन के संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर03054 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया 1,40,40,000/-लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-1. अधियाचना प्रपत्र

2. IRI Report

विश्वासभाजन

ह0/-

कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

झापांक-1333/बाँका दिनांक 04/08/2021 .

प्रतिलिपि :- मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

82.08.21
कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

Form GFR 19-A

(See Government of India's Decision (1) below rule-15)
Form of utilization Certificate up to the Month June' 2021
MR/3054(NEW MAINTENANCE POLICY)

PIU-RWD(W), BANKA-2

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural roads under MR/3054(NEW MAINTENANCE POLICY)	विभागीय पत्रांक 37 दिनांक 27.05.2020 45(Encl)/18.06.2020 56(Encl)/12.08.2020 59(Encl)/18.08.2020 61(Encl)/26.08.2020 82(Encl)/13.11.2020 84(Encl)/26.11.2020 86(Encl)/11.12.2020 05(Encl) /12.01.2021 17 (Encl) / 26.02.2021 20 (Encl) /19.03.2021 22(Encl) /24.03.2021 27(Encl) /04.05.2021 30 (Encl) /21.05.2021 32 (Encl) / 28.05.2021	217.86340 30.12339 525.63100 320.50000 6.57325 88.44000 395.49360 368.11196 570.35090 604.70836 361.33115 82.05330 88.60000 58.28940 440.19502	Certified that out of Rs. 4158.26473 Lacs received during the years 2020-21 in favour of Ex. Engineer. RWD Bihar, RWD-2 Banka a sum of Rs. 4137.93652 Lacs has been utilized for the purpose of MR/3054(New Maintenance Policy) schemes as given in the margin for which it was sanctioned and that the balance of Rs 20.32821 remaining unutilized at the end of the period under.
	Total		4158.26473	


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer .
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Measurement have been recorded in the MBs.
- All other code formalities have been observed.

3. Physical progress achieved :

- Construction of Road Works.
- Construction of CD Works.


Sr. D.A.O.
Works Division Banka-II
Rural Works Department


Executive Engineer
Works Division Banka-II
Rural Works Department

Requisition Format for Scheme Head-MR (3054) Under Bihar Rural Road Maintenance Policy 2018 (Initial Rectification and Surface Renewal)
 Name of Division :- Banka-2

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion (Expected)	Value of IRI (in mm/km)	Thickness of Bitumen layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lac)	Up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial rectification on with Surface renewal (in lac)	5 Years Routine Maintenance (in lac)										
1	MR-N/19-20 Banka-2/26 under 3054/MR	Katoriya Baliyama Road To Sathiyari	20703602048	6276 02.12.2019	1.500	58.637	38.07673	14.85633	44/MBD/20-21 24.09.20	23.09.21	31.07.2021	2916.400	25mm	5%	0.00000	0.00000	38.00000	Completed
2	MR-N/19-20 Banka-2/24	Repair of Road from Sanhaula-Panjwara To Chormara under MR/3054	20703502117	6276 02.12.2019	4.137	153.633	102.45565	41.44152	11/MBD/20-21 15.07.2020	14.07.21	31.07.2021	2703.267	25mm	5%	0.00000	0.00000	102.40000	Completed
		Total															140.40000	

02.08.21
 Executive Engineer
 R & D (W) Division
 Banka-2

Lab Job number :38

Date :31.07.2021

Name of Customer :

Sudesh Kumar Singh & Co. Const.Pvt. Ltd.

Name of Work/ Road :

Sanhaul Panjwara to Chormara under MR 3054 New
Maint Policy 2018

Sr.no	Location of test(in km)	Corrected U.I value(mm/km)	Road catagory
1	0.1	2400	G
2	0.2	3175	G
3	0.3	3175	G
4	0.4	2303	G
5	0.5	2497	G
6	0.6	2690	G
7	0.7	2884	G
8	0.8	2400	G
9	0.9	2981	G
10	1.0	2787	G
11	1.1	2109	G
12	1.2	2690	G
13	1.3	2497	G
14	1.4	2787	G
15	1.5	3466	G
16	1.6	3175	G
17	1.7	3078	G
18	1.8	2981	G
19	1.9	3659	G
20	2.0	2109	G
21	2.1	2593	G
22	2.2	2497	G
23	2.3	1818	G
24	2.4	2012	G
25	2.5	2787	G
26	2.6	2497	G
27	2.7	2884	G
28	2.8	2690	G
29	2.9	2593	G
30	3.0	2884	G

for 21/8/21
JS

for 02.08.21

EXECUTIVE ENGINEER
R.W.D. (W) Division
Barka-2

Lab Job number :38

Date :31.07.2021

Name of Customer :

Sudesh Kumar Singh & Co. Const.Pvt. Ltd.

Name of Work/ Road :

Sanhaul Panjwara to Chormara under MR 3054 New
Maint Policy 2018

31	3.1	2206	G
32	3.2	1915	G
33	3.3	1624	G
34	3.4	2981	G
35	3.5	2012	G
36	3.6	2593	G
37	3.7	3950	G
38	3.8	3756	G
39	3.9	2981	G
40	4.0	2884	G
41	4.1	2206	G
42	4.2	1915	G

[Signature]
21/8/21
Junior Engineer

Assistant Engineer
R.W.D Works Division
Banka-2

[Signature]
02.08.21
Executive Engineer
R.W.D Works Division
Banka-2

Name of Customer : Sudesh Kumar Singh and Construction Pvt Ltd
Name of Work/Road :Sanhauia Panchwara to Chormara under MIR 3054

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	UIV	CATEGORY ROAD	IRI	Latitude	Longitude	Event
31/7/21	7:40:16	38	0.1	240	0	2400	2400	G	3.3	24.97700	87.13060	Normal
31/7/21	7:40:51	38	0.1	320	20.2	3200	3175	G	4.23	24.98114	87.13362	Normal
31/7/21	7:42:2	38	0.1	320	20.2	3200	3175	G	4.23	24.94792	87.70370	Normal
31/7/21	7:43:0	38	0.1	230	20.2	2300	2303	G	3.18	24.94716	87.70588	Normal
31/7/21	7:43:48	38	0.1	250	20.2	2500	2497	G	3.42	24.94636	87.70302	Normal
31/7/21	7:44:23	38	0.1	270	20.2	2700	2690	G	3.65	24.94548	87.70150	Normal
31/7/21	7:45:0	38	0.1	290	20.2	2900	2884	G	3.88	24.94570	87.71110	Speed Breaker
31/7/21	7:45:34	38	0.1	240	20.2	2400	2400	G	3.3	24.94493	87.72053	Normal
31/7/21	7:46:9	38	0.1	300	20.2	3000	2981	G	4	24.94457	87.72962	Normal
31/7/21	7:46:44	38	0.1	280	20.2	2800	2787	G	3.77	24.94416	87.73838	Normal
31/7/21	7:47:19	38	0.1	210	20.2	2100	2109	G	2.94	24.94377	87.74730	Normal
31/7/21	7:47:19	38	0.1	270	20.2	2700	2690	G	3.65	24.94337	87.75538	Normal
31/7/21	7:48:0	38	0.1	250	20.2	2500	2497	G	3.42	24.94288	87.76312	Speed Breaker
31/7/21	7:48:30	38	0.1	280	20.2	2800	2787	G	3.77	24.94226	87.76935	Normal
31/7/21	7:49:5	38	0.1	350	20.2	3500	3466	G	4.58	24.94142	87.76598	Normal
31/7/21	7:49:41	38	0.1	320	20.2	3200	3175	G	4.23	24.94054	87.76278	Normal
31/7/21	7:49:41	38	0.1	310	20.2	3100	3078	G	4.12	24.93970	87.76060	Speed Breaker
31/7/21	7:50:0	38	0.1	300	20.2	3000	2981	G	4	24.93880	87.75908	Normal
31/7/21	7:50:16	38	0.1	370	20.2	3700	3659	G	4.8	24.93792	87.75690	Normal
31/7/21	7:50:16	38	0.1	210	10.1	2100	2109	G	2.94	24.93706	87.75487	Normal
31/7/21	7:50:51	38	0.1	260	20.2	2600	2593	G	3.53	24.93617	87.75337	Normal
31/7/21	7:51:0	38	0.1	250	20.2	2500	2497	G	3.42	24.93531	87.75150	Normal
31/7/21	7:51:0	38	0.1	180	30.3	1800	1818	G	2.57	24.93449	87.74948	Speed Breaker
31/7/21	7:51:26	38	0.1	200	20.2	2000	2012	G	2.82	24.93381	87.74377	Curve
31/7/21	7:51:26	38	0.1	280	20.2	2800	2787	G	3.77	24.93310	87.74192	Normal
31/7/21	7:51:26	38	0.1	250	10.1	2500	2497	G	3.42	24.93225	87.74192	Normal
31/7/21	7:52:2	38	0.1	290	20.2	2900	2884	G	3.88	24.93153	87.74713	Speed Breaker
31/7/21	7:52:2	38	0.1	270	20.2	2700	2690	G	3.65	24.93074	87.75168	Normal
31/7/21	7:52:37	38	0.1	260	20.2	2600	2593	G	3.53	24.92990	87.75538	Normal
31/7/21	7:52:37	38	0.1	290	20.2	2900	2884	G	3.88	24.92904	87.75387	Normal
31/7/21	7:53:12	38	0.1	220	20.2	2200	2206	G	3.06	24.92814	87.75318	Normal
31/7/21	7:53:12	38	0.1	190	20.2	1900	1915	G	2.7	24.92729	87.75100	Normal
31/7/21	7:53:12	38	0.1	160	20.2	1600	1624	G	2.33	24.92642	87.75150	Normal
31/7/21	7:54:0	38	0.1	300	20.2	3000	2981	G	4	24.92552	87.75070	Normal

Y = 0 * X ^ 2 + 0.969 * X + 74.60
X = 1900
Y = 1915
(R) RURAL ROAD
Good
Average 4001-5000
Poor >5001

21/8/21

02.08.21
EXECUTIVE ENGINEER
R.W.D. (M) Division
Barkhede

Name of Customer : Sudesh Kumar Singh and Construction Pvt Ltd
Name of Work/Road : Sanhaula Panchwara to Chormara under MR 3054

Sannaula Panchwara to Chormara under MR 3054									Lab Job No: 38				
Date	Time	Section	Length in km	Bumps in mm	Speed Rate	OR mm/km	UIV	CATEGORY ROAD	IRI	Latitude	Longitude	Event	
		No.											
31/7/21	7:54:0	38	0.1	200	20.2	2000	2012	G	2.82	24.92513	87.75958	Normal	
31/7/21	7:54:23	38	0.1	260	20.2	2600	2593	G	3.53	24.92490	87.76885	Normal	
31/7/21	7:54:23	38	0.1	400	10.1	4000	3950	G	5.14	24.92523	87.77693	Speed Breaker	
31/7/21	7:55:33	38	0.1	380	10.1	3800	3756	G	4.92	24.95674	87.14353	Normal	
31/7/21	8:2:0	38	0.1	300	20.2	3000	2981	G	4	24.95674	87.14353	Normal	
31/7/21	8:2:28	38	0.1	290	20.2	2900	2884	G	3.88	24.95590	87.14362	Speed Breaker	
31/7/21	8:2:28	38	0.1	220	20.2	2200	2206	G	3.06	24.95592	87.14362	Normal	
31/7/21	8:3:3	38	0.1	190	20.2	1900	1915	G	2.7	24.95579	87.14330	Normal	

Junior Engineer

[Signature]
21/8/21

Assistant Engineer
Rural Works Department
Works Division, Banka-2

Executive Engineer
Rural Works Department
Works Division, Banka-2

[Signature]
22.08.21

Name of Customer : **Sudesh Kumar Singh and Co C**
 Name of Work/Road : **Sanhaula Panchwara to Chormara**
 Lab Job number : **38**
 Date : **31-07-2021**
 Section No. : **38**


Print
 Generate Report and Graph

Test Date : **31-07-2021**
 Machine No : **407**
 Start S No :
 Start E No :
 Weather :
 Start Location : **24.97700,87.13**
 End Location : **24.95579,87.14**
 Road Name : **Sanhaula Panchwara to Chormara**
 Road Type : **(R) RURAL ROAD**
 Side :
 UV Range : **624 To 5000**
 Dist Range : **0 To 4.3**
 Equation : **$Y = 0 \cdot X^2 + 0.969 \cdot X + 74.60$**
 Interval : **1000** mm/km
 * 1000 m

Redraw Graph

Map View

File : t:\BUmp Integrator Report\Sudesh Kumar Singh Pvt Ltd\SUDESH.xlsx
 Name of Customer : **Sudesh Kumar Singh and Co Construction**
 Name of Work/Road : **Sanhaula Panchwara to**




Distance - 1000 m

31/8/21

31/8/21

EXECUTIVE ENGINEER
 R.W.D. (W) Division
 Banke-2

2/8/21



EXECUTIVE ENGINEER
R.W.D. (W) Division
Banka-2

2/8/21