

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 29.11.2021

District: *Muzaffarpur*

Division: *Muzaffarpur East 1*

Length (km): 8.200

Name of the Road: *Repair of Road from Chaurama to Talgachia*

Scheme/Programme: *NR-3054*

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U

Observation Remarks:- *Surface Condition is badly damaged. In Recent flood in 2021-22, the surface of road is submerged by water in maximum length of the road as told by the villagers.*

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	NO ATR.

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Unsatisfactory (U)

Name of Officer:- *Rana Binay Kumar Singh*

Designature:- *Executive Engineer
RWD, Regional Lab Bhagalpur.*

[Signature]
(Signature)

EE Muzaffarpur East 1, Sri Gyan Bilhaka