

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 11/12/2021

District: Supaul

Division : Viro Pur

Length (km): 2.36

Name of the Road: Repair of Road from Situhars to Baisi Border

Scheme/Programme: M/R

Sl. No.	Parameters to be checked	Remarks (NT)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:- Flank damaged due to flood. At charge standing point and 60m protection work and restoration work done with bamboo, sand bags and brick bats.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & John stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (Remarks present)

11/12/21
A.E.
Bidy Rajak
Executive Engineer
R.W.D.
Regional Job
Don't forget