

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 15.12.2021		District: Kabhar
Division : Baran		Length (km): 3.20
Name of the Road: Bighar Hat to Pale Tola		
Scheme/Programme: NABARD		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any No rain cuts.	S
Observation Remarks:- Surface Condition is Satisfactory. In flank there is no rain cuts.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- Rama Baran Kumar Singh
 Designature:- Executive Engineer, Regional Lab. Bageshwar.


 15.12.2021
 (Signature)