

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 17.12.2021	District: Kabhas
Division : Barot	Length (km): 2.473
Name of the Road: Balia To Bandhahaban Sadapur gaon via Harnathpur	
Scheme/Programme:	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any No rain cuts.	S

Observation Remarks:- Surface condition is satisfactory. In approx 50m length of one side of the flank, Temporary Retention work done by brick least for the protection of flank.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- Rana Brahm Kumar Singh
 Designation:- Executive Engineer, Regional Lab. Bhagalpur.

17.12.2021
 (Signature)