INSPECTION REPORT FOR ROUTINE MAINTENANCE

	Inspection: 14/12/2021 District: Augar	iga bad
	1: Aurangabad Length (km): 0	186 KM
Name of	Tthe Road: Soundarganj Dudhar Damru	Road Cradhpas
Scheme/	Programme: MMGSY[Gen]	
SI. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible crack aggregates in case of CC Pavement.	ks, exposed
e)	Contraction Joints provided or not (CC Pavement)	_ S
f)	Compaction of flank/slope & raincuts if any	S
2		
2.	Cross Drainage	
a)	Cross Drainage Condition of head walls in Hume pipe culverts including	g its painting S
	<u> </u>	
a)	Condition of head walls in Hume pipe culverts including	verts –
a) b) c) d)	Condition of head walls in Hume pipe culverts including Condition of Abutment & Wing walls, Slab in RCC cult Condition of railings/slab/approach for Bridges Condition of Vent Clearance	verts —
a) b) c) d)	Condition of head walls in Hume pipe culverts including Condition of Abutment & Wing walls, Slab in RCC cul- Condition of railings/slab/approach for Bridges	verts –
a) b) c) d)	Condition of head walls in Hume pipe culverts including Condition of Abutment & Wing walls, Slab in RCC culton Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:-	verts –
a) b) c) d) Observa	Condition of head walls in Hume pipe culverts including Condition of Abutment & Wing walls, Slab in RCC culton Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:- Main fained	verts – S
a) b) c) d) Observa 3.	Condition of head walls in Hume pipe culverts including Condition of Abutment & Wing walls, Slab in RCC cult Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:- Main famed Road Furniture Whether sign boards/informatory/cautionary Board/ In	xm & 200m ained
a) b) c) d) Observa	Condition of head walls in Hume pipe culverts including Condition of Abutment & Wing walls, Slab in RCC culton of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:- Main fained Road Furniture Whether sign boards/informatory/cautionary Board/ Is stones/Pavement road markings are provided and maintain	xm & 200m ained
a) b) c) d) Observa 3. a)	Condition of head walls in Hume pipe culverts including Condition of Abutment & Wing walls, Slab in RCC cult Condition of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:- Main famal Road Furniture Whether sign boards/informatory/cautionary Board/ Is stones/Pavement road markings are provided and maintain ation Remarks:- Over all road main feation Remarks:-	xm & 200m ained
a) b) c) d) Observa 3. a) Observa 4. a)	Condition of head walls in Hume pipe culverts including Condition of Abutment & Wing walls, Slab in RCC cultion of railings/slab/approach for Bridges Condition of Vent Clearance ation Remarks:- Main famed Road Furniture Whether sign boards/informatory/cautionary Board/I stones/Pavement road markings are provided and maintain ation Remarks:- Over all road main famed Compliance History	xm & 200m S ained Salusfoetar

mar Rakesh तकनीकी सलाउकार प्रामीण कार्य दिणाग कार्य शंबरा, ५४०

Designature:-

(Signature)