

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1

Email ID:-ee.rwd.sasaram1@gmail.com

Mob:- 8986915310

पत्रांक..... 207 3330 सासाराम/दिनांक 02.02.2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

सेवामें,

नोडल पदाधिकारी (MR 3054)
ग्रामीणकार्यविभाग
पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु० :- यथोक्त।

विष्वासभाजन

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

02/02/21
Deputy Engineer
G.W.D.(W) Div. Sasaram-1

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to Feb 2021

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA Letter No.82, dt. 13.11.2020 Letter No.84, dt. 26.11.2020 Letter No.86, dt. 11.12.2020 Letter No.05, dt. 12.01.2021	24012800.00 19457900.00 65864300.00 142175100.00	Certified that out of Rs. 25,15,10,100.00 lakh of grants-in-aid sanctioned during the years 2020-21 Infavor of EE,RWD works division Sasaram-1 a sum of Rs 162385738.00 lakh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 87103358.00 lakh remaining unutilized at the end of the period under report.
	Total:		25,15,10,100.00	


2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.


Kind of Checks exercised:-


- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other caudal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD works.


Divisional Accounts Officer
R.W.D, works Division
Sasaram-1
Sr. Divnl. Accounts Officer
R.W.D. Division, Sasaram-1


Executive Engineer
R.W.D, works Division
Sasaram-1


Executive Engineer
R.W.D, works Division
Sasaram-1
02/02/21

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SASARAM-1

Requisition Format for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- Sasaram-1

Sl no.	Package No	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount		Agreement No& Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Amount Allotted (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	9	Sasaram Chausa Tilakapur - Basadha	10301002140	3021 16.07.2019	2.820	82.75660	52.644	14.77211	42/MBD/ 2020-21 22.02.20	21.11.2020	-	2515	25.00	5.03	0.00000	0.00000	52.64400	
Total					2.820	82.75660	52.644	14.77211							0.00000	0.00000	52.64400	

26/07/21
Divisional Accounts Officer
Rural Works Department,
Works Division, Sasaram-1
St. Divnl. Accounts Officer
R.W.D. Division, Sasaram-1

24/07/21
Executive Engineer
Rural Works Department
Works Division, Sasaram-1
02/02/21
Executive Engineer
R.W.D.(V)Dt. Sasaram-1


Name of Customer: Lailan Sukla
Name of Work/Road: Sasaram Chausa Tilakpur to B
Lab Job number: 18
Date: 1/15/2021
Section No.: 18

Test Date: 1/15/2021
Machine No.: 391
Start S No.: 7311
Start E No.: 7338
Weather: Normal
Start Location: 25.76335, 83.94
End Location: 25.7547, 83.922
Road Name: Sasaram Chausa Tilakpur to B
Road Type: (R) RURAL ROAD
Side: Kangahar
Interval: 1000
U/V Range: 415 To 4000
Dist Range: 0 To 0.012
Equation: $Y = 0 * X^2 + 1.000 * X + 415.2$

Print Generate Report and Graph

Redraw Graph

Map View



W
 2/2/21
 Executive Engineer
 A.W.D.(V) Div. Sasaram-1

Name of Road : Sasaram Chausa Tilakpura - Basadiha

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	EGORY ROAD	Latitude	Longitude	Event
15/1/21	13:41:8	18	0.1	100	23.1	1000	1415	G	25.76335	83.94123	Normal
15/1/21	13:41:43	18	0.1	110	10.1	1100	1515	G	25.76725	83.94027	Normal
15/1/21	13:42:0	18	0.1	220	21.3	2200	2615	G	25.7701	83.93933	Speed Breaker
15/1/21	13:42:18	18	0.1	270	31.1	2700	3115	G	25.76715	83.9387	Normal
15/1/21	13:43:0	18	0.1	200	22.3	2000	2415	G	25.7584	83.93854	Normal
15/1/21	13:43:0	18	0.1	110	20.2	1100	1515	G	25.74957	83.93838	Curve
15/1/21	13:43:29	18	0.1	220	20.2	2200	2615	G	25.74938	83.93746	Normal
15/1/21	13:43:29	18	0.1	280	30.3	2800	3215	G	25.7509	83.9365	Normal
15/1/21	13:43:29	18	0.1	210	20.2	2100	2515	G	25.75335	83.93542	Normal
15/1/21	13:44:4	18	0.1	290	10.1	2900	3315	G	25.75312	83.93456	Normal
15/1/21	13:44:4	18	0.1	190	10.1	1900	2315	G	25.74862	83.93397	Normal
15/1/21	13:44:39	18	0.1	260	10.1	2600	3015	G	25.74993	83.93296	Normal
15/1/21	13:45:0	18	0.1	140	20.2	1400	1815	G	25.75242	83.93204	Normal
15/1/21	13:45:15	18	0.1	280	20.2	2800	3215	G	25.75365	83.93108	Normal
15/1/21	13:45:15	18	0.1	100	20.2	1000	1415	G	25.76162	83.93077	Normal
15/1/21	13:45:50	18	0.1	250	20.2	2500	2915	G	25.77063	83.93076	Normal
15/1/21	13:46:0	18	0.1	190	20.2	1900	2315	G	25.77597	83.93027	Normal
15/1/21	13:46:25	18	0.1	240	10.1	2400	2815	G	25.77673	83.92919	Normal
15/1/21	13:46:25	18	0.1	280	10.1	2800	3215	G	25.7782	83.9282	Normal
15/1/21	13:47:0	18	0.1	150	20.2	1500	1915	G	25.7787	83.92729	Normal
15/1/21	13:47:35	18	0.1	170	20.2	1700	2115	G	25.78192	83.92524	Normal
15/1/21	13:48:0	18	0.1	210	20.2	2100	2515	G	25.78342	83.92428	Normal
15/1/21	13:48:10	18	0.1	110	20.2	1100	1515	G	25.785	83.9233	Normal
15/1/21	13:48:45	18	0.1	270	10.1	2700	3115	G	25.77957	83.92298	Normal
15/1/21	13:49:0	18	0.1	200	20.2	2000	2415	G	25.77063	83.92286	Normal
15/1/21	13:49:21	18	0.1	230	20.2	2300	2715	G	25.76157	83.92271	Normal
15/1/21	13:49:21	18	0.1	210	20.2	2100	2515	G	25.7547	83.92261	Curve
Total			2.8								

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2100$$

$$Y = 2515$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

Signature
A. V. B. (V) Dtr. Sasaram-1