

Schedule XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D.	
② Labour for driving 60 mm to 75 mm dia Bamboo piles including cutting to in proper size and shoes etc					
	40 m	133 m			
	0.3				
	Total 133 m x 4 = 532 m				
	Required value = $\frac{532}{0.3} = 1773 m$				
③ Supplying, fitting & fixing of Bamboo 62 mm to 75 mm dia - do -					
- do -					
Qty - 2 x 133 m = 1066 m					

④ Supplying, fitting in position & plot bamboo woven chanchang					
- do -					
Qty - 133 m x 1.5 m = 199.5 m ²					

⑤ providing and laying Reinforced Cement Concrete pipe NP3 For Restoration (1000 mm dia in Single Row) -					
Qty - 3 x 2.5 m = 7.5 m					

30/11/2020
J.E.

Executive Engineer,

Rural Works Department
Works Division Dhamdaha (Purnea)

Date:

Inspection Report for flood damage work

1. Name of PIUs- Dhambala

2. Name of Block/Road- Karahar Kethi/LOS2 to Jangal Naya tola

A. For Road

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

53.20 M

Road wash out due to flood

Bamboo, Brick bats, Hume pipe

Tractor

Manual

53.20 M

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

Signature of JE/AE/EE

[Signature]
28/1/24
JE

[Signature]
28.01.24
EE

Signature

(Name of Inspector)

[Signature]
28/1/24

[Signature]
28/01/2024
J-E