


FIELD INSPECTION REPORT

Date of Inspection: 03/01/21	District: East Champaran
Division: Arroy	Length (km):
Name of the Road: Kishin Tola To Baymasawa Ghumhar Tola	
Scheme/Programme: MAINTENANCE	
Package No.:	Read Id No: 51708312006
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be Inspected	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
	Culverts	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
	Signage	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
	Other	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


 (Signature)

NAME: Harendra Kumar

DESIGNATION: SRI
 Rtd Arroy

Scanned with CamScanner