

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(6) <u>Repaired Concrete</u>					
(7) <u>Loose cement layer</u>					
17 scft <u>removed</u>					
<u>and left</u>					
<u>Cft w/cp T PDB P - 33</u>					
<u>Cft = 8.0703</u>					
<u>Rp. 6370.01 - Rp 51532.00</u>					
<u>(8) Draining Spots</u>					
<u>3 complete layers of cleaning</u>					
<u>and removed</u>					
<u>13 scft T PDB P - 33</u>					
<u>Cft = 8.40 x 1.372.97</u>					
<u>- Rp 3183.76</u>					
<u>Rp. 8429786.65</u>					
<u>Add 4% T 29.67</u>					
<u>rp per Agreed 81011570.80</u>					
(L.C) <u>1 Y.M. 84297.56</u>					
<u>Rp. 95257655.04</u>					
<u>before 0.72%</u>					
<u>Rp. 73347.31</u>					
<u>Rp. 7452277.73</u>					
<u>Tax 1912069.00</u>					
<u>Net Rp. 7540208.73</u>					
<u>Net Rp. 7540209.00</u>					
<u>Repaired 1/12/2021</u>					
<u>26/12/21</u>					

Continuation ACCap 2021

22/07 APC B11

30

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Length of Road :- 40m					
Beg. Leng. Dangay Seeluk					
To Udaivilayi Deep					
Area of road path					
Area of Pucca m. R.L. 40					
Area of Tsl. Measuring Tsl.					
Area of Tsl. Measuring Tsl.					
Total = 40m x 40m (40)					
Agency 2 A.Lok Kumar					
Agreement - 26500 Rs 26-2					
Date of Survey - 13/07/2000					
Comp - 13/07/2000					

Record of Survey

① Description - Boundary	
Left of Cyl 1A X 0.67 M	
Middle green - - - - - do	
— — — — — do	
For B portion 350 m	
Up 0.67 x 30.67 x 0.50 = 15.00	
Up 0.67 x 30.67 x 0.50 = 18.90	
Up 1 x 26.67 x 0.50 = 13.33	
for P.C. portion 5.00	
Up 1 x 0.67 x 0.33 x 0.50 = 0.50	
Up 1 x 15.67 x 0.33 x 0.50 = 1.125	

Continuation

Up 1 x 0.67 x 0.33 x 0.50 = 0.50

Up 1 x 0.67 x 0.33 x 0.50 = 0.50

Part 1 60.575 m<sup>2</sup>

15(10) AE