

FIELD INSPECTION REPORT

Date of Inspection :	29/12/20	District:	East Champaran
Division :	Motikari	Length (km):	2.612 Km.
Name of the Road:	Scp road Sakhi to Suriswar		
Scheme/Programme:	MAINTENANCE / MMGSY (SC)		
Package No.:	—		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	✓/U
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	✓SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U -MA-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U -MA-
c)	Condition of railings/slab/approach for Bridges	S/SRI/U -MA-
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

Prady
30/12/20
(Signature)

NAME: Maheshwar Sharma

DESIGNATION: J.E.