

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar
2. Name of Block/Road - mirzapur / sheohar pnd road to surajm pakega


A. For Road

1. Damage Location/Chainage : 0+02m, 0+100km, 0+180 km, 0+300km, 0+800km, 1.5 km, 4.6km
2. Damage Length : 141.50 m (0.1415 km)
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick bats & local sand
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 141.50 m (0.1415 km)

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE


18-11-20
Signature

(Name of Inspector)

EE
RWD WORKS DIVISION PURVI-1 MUZAFFARPUR

GENERAL ABSTRACT

Name of Road Sheohar PWD Road to Surjan Pakari

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 1.651 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	14.034
2	Sand Filling	0.129
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	14.163
TOTAL COST OF PROJECT IN LACS =		14.163

12.371

12.50

12.50

say 12.50 lac

Ramath
11/11/2022

JE
RWD

A. S.
11/11/22

AE
RWD

g. S.
11/11/22

EE
RWD

Technically approved for Rs 12.50 lac
(Rupees Twelve lac fifty thousand only)

Shm
12.12.22

SE

RWD work circle
muzaffarpur