


# FIELD INSPECTION REPORT

Date of Inspection : 07-01-2021	District: <del>CHHATTISGARH</del> GAYYA
Division : RWD, Tekan	Length (km): 0.794km
Name of the Road: L118 EKRIYA to LALIYA	BigHA (vr-118)
Scheme/Programme: MAINTENANCE	PMGISY
Package No.: BR-12R-942	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Under maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance	N.C

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U - S
b)	Condition of Surfacing	S/U - S
c)	Riding Quality	S/U - S
d)	Road Camber	S/U - S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No - Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U -
c)	Condition of railings/slab/approach for Bridges	S/SRI/U -
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained 200m	Yes/No - Yes
4.	Compliance History	
a)	Status of ATR's & any others	N/A -

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

  
(Signature)

NAME: SUBHASH KUMAR