## Inspection Report For Flood Damage Work

Date: 21.12.2020. 1. Name of PIUs - Executive Engineer, Rud(w) Division, Banko-2. 2. Name of Block Road: Dhorailya, Baijnothpur to Baidpur A. For Road 1. Damage Location/Chainage : - 0 - 250 km 2. Damage length : - 6-037 KM 3. Nature of Damage : Heavy experiendue to heavy rain fall and

ever topping flow of are viver water 4. Detail of Restoration Works: (i) Material being used in Restoration Works:

(ii) Equipment's/ Tools Being used in Restoration Works:

(iii) Procedure Taken up in Restoration Works:

(iv) Restored Length: - 0.037 km

B. For Bridge

1. Damage Location/Chainage

2. Damage length

3. Nature of Damage

4. Detail of Restoration Works

(i) Material being used in Restoration Works:

(ii) Equipment's/ Tools Being used in Restoration Works:

(iii) Procedure Taken up in Restoration Works:

(iv) Restored Length:

(i) Name of Road: Baijnathpus to Baidpus C. Requirement Of New C&Bridges

(ii) Location/Chainage : 0.250km

(iii) Type of CD Work/Length required : HLB 87.669.

 Upload one Photograph of damaged portion if available · Attach minimum Two Photograph (during restoration & after

restoration) Photographs should be Geotags and at Least one Photo be captured in selfie mode.

Segmente et JE/AE/EE Hatt

(Name of Inspector)

## Inspection Report For Flood Damage Work

21.12.2020. 1. Name of PIUs - Executive Engineer, LWD(w) Division, Banka-2. 2. Name of Block/Road: Phoraiga, Baijnathpur to Baidpur A. For Road 1. Damage Location/Chainage : - 6 · 250 km 2. Damage length : - 6.037 Km :- Heavy errosion due to heavy rain fall and 3. Nature of Damage over topping blow of arm river water 4. Detail of Restoration Works : Material being used in Restoration Works: (ii) Equipment's/ Tools Being used in Restoration Works: (iii) Procedure Taken up in Restoration Works: (iv) Restored Length: - 0.037 Km B. For Bridge 1. Damage Location/Chainage 2. Damage length 3. Nature of Damage 4. Detail of Restoration Works (i) Material being used in Restoration Works: (ii) Equipment's/ Tools Being used in Restoration Works: (iii) **Procedure Taken up in Restoration Works:** Restored Length: (iv) C. Requirement Of New CD/Bridges Baijnathpur to Baidpur Name of Road: (i) (ii) Location/ Chainage : 0.250 km Type of CD Work/Length required ' HLM 87.66 %. (iii) Notes:- Upload one Photograph of damaged portion if available Attach minimum Two Photograph (during restoration & after restoration) Photographs should be Geotags and at Least one Photo be captured in selfie mode. 21/12/20 Air 2020 21/12/2020 Signature of JE/AE/EE (Namé of Inspector)

## अधीक्षण अभियंता का कार्यालय

ग्रामीण कार्य विभाग, कार्य अंचल, भागलपुर।

पत्रांक 1519 अन्।

मागलपुर, दिनांक ... 26/12/2020.

TOM

Culve

28 heal

Wor

Wor

ak

ng

प्रेषक:--

अधीक्षण अभियंता, ग्रामीण कार्य विभाग, कार्य अंचल, भागलपुर ।

सेवा में,

नोडल पदाधिकारी, F.D.R. ग्रामीण कार्य विभाग, पटना, बिहार।

विषय:-

FDR योजनान्तर्गत पथ के प्राक्कलन का तकनीकी अनुमोदनोपरांत प्रशासनिक स्वीकृति के संबंध में।

प्रसंग:-

कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, बाँका—2 का पत्रांक— 3995 अनु0 एवं 3996 अनु0, दिनांक— 24.12.2020।

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के संबंध में कहना है कि कार्य प्रमंडल बाँका-2 से प्राप्त FDR योजनान्तर्गत निम्नलिखित पथ के प्राक्कलन को तकनीकी अनुमोदनोपरांत प्रशासनिक स्वीकृति हेतु समर्पित किया जा रहा है, जिसकी विवरणी निम्न प्रकार है :--

क्रमांक	प्रखण्ड	पथ का नाम	लम्बाई (मी०)	प्राक्कति राशि (लाख में)	
1	Katoriya	L070 Malwarichak to Hethmathiya.	25 m	2.216	
2	Dhoraiya	Baijnathpur to Baidpur	<b>37</b> m	3.612 7 <del>86</del> 9	

SITO:— UNITATION CONTRACTOR CONTR

विश्वासभाजन

अधीर्मण अमियंता ग्रामीण कार्य विभाग, कार्य अंचल, भागलपुर।

# वामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR REPAIRING OF ROAD F.D.R. (2020 - 21)

## DETAILED ESTIMATE FOR F.D.R. RESTORATION WORK

DISTRICT:	Banka	Banka		LOCK : Dhoraiya	
NAME OF ROAD:	Baijnathpur	o Baidpur.			
otal Length of road		:	37 m	KMS	
tal cost of FDR. part -	:	3.168	LACS		
1 G.S.T. @ 12 %		0.380	LACS		
dd labour cess @ 1%		:	0.032	LACS	
Add SF @ 10%		:	0.032	LACS	
0.0.0		:	3.612	LACS	

### SUBMITTED BY

The Executive Engineer Works Division, Banka-2

#### **GENERAL ABSTRACT OF COST**

Name of Road

: Baijnathpur to Baidpur.

District: Banka

Length

37 m

Block: Dhoraiva

for Re ocemen cincion Works

I in Res Being u

Resto

Stora

16

Zengen			Diock . Diformly			
SI. No	Particulars		Details	Total Cost (in Rs.)		
1	Cost of Road Restoration work	:	37 m	3,16,762.00		
2	Add G.S.T @ 12 %	:		38,011.00		
3	Add L.C. @ 1 %	:		3,168.00		
4	S. F. @ 10 %	:		3,212.00		
	Total Cost of Restoration work	:		3,61,153.00		
			Say,	3,61,153.00		

14 3,61,2W 200

Technology Approved for & 3,61,2w 2w (Rupay)
Three loe Stroty on thousand two hundred July,

R.W.D. (Works) Circle Bhagalpur