

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - *Gyan vibhakar*
2. Name of Block/Road - *muzaffarpur/ muddu route to purnia road*

A. For Road

1. Damage Location/Chainage : *0.200km, 0.300km, 0.500km, 0.600km*
2. Damage Length : *0.135km Approx (134.5 m)*
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : *Brick bats flood sand*
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : *0.135km (0.1345 km)*

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

18/11/20

Signature

(Name of Inspector)

EE

*RWD WORK DIVISION
muzaffarpur East-1*

GENERAL ABSTRACT

Name of Road Guddu House to PMGSY Road

District Muzaffarpur


Block Minapur

Division Muzaffarpur East-2


Length of Road (in Km) 0.900 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	31.771
2	Sand Filling	0.289
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	32.060
TOTAL COST OF PROJECT IN LACS =		32.060


say 32.06 lac


11/11/2020

JE
RWD



11/11/20

AE
RWD


11/11

RWD

Technically approved for Rs 32.06 lac
(Rupees Thirty two lac six thousand only)


12.12.20
SE

RWD work circle
muzaffarpur