FIELD INSPECTION REPORT

| | FIELD INSPECTION REPORT | | |
|------------|---|----------------------------|------------------------|
| Date | of Inspection: 0.5-01-2021 District: NAWA | DA | 7 |
| Divisi | on: RAJAULI Length (km): 1-523 | | - |
| Name | of the Road: FATEHPUR GOBINDPUR PATH | TOKARMA | 711 |
| Schen | ne/Programme: MAINTENANCE DM INCV | | |
| Packa | ge No.: BR25R-617 Road Id No.: 1050270 | 0241 | 100 |
| Status | of the Project: Ongoing/Completed/Under Maintenance | | |
| -MAN 275 A | is a case of: New Connectivity/Up gradation/ Muintenance | | |
| SI No | Parameters to be checked | Remarks | |
| 1. | Pavement | The second second | |
| a) | Road Junction condition | S/U | 7 |
| b) | Condition of Surfacing | S/U | N/A |
| · c) | Riding Quality | S/U | |
| d) | Road Camber | S/U | Yet not |
| c) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Ycs/No | Dua 20 |
| Ŋ | Contraction Joints provided or not (CC Pavement) | Yes/No | private low Dispute |
| g) | Compaction of flank/slope & raincuts if any | Yes/No | Bolowe |
| 2, | Gross Drainnee | 90 - 35 200 - 350 - 340 | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U | N/A Work yet |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U | Not Started |
| 3 | Road Furniture | | due to priva |
| a) s | Whether sign boards/informatory/cautionary Board/km & 200m tones/Pavement road markings are provided and maintained | Yes/No | N/A |
| in c | Outpilluse History | | work yet |
|) S | tatus of ATR's & any others | Q- 19-1 | Started. |
| mil Das | ing | | due to prive |
| rall Rat | Satisfactory (S) | | MA WOYK Y |
| | Satisfactory but requires Improvement (SRI) | | not starte |
| | Unsatisfactory (U) | | due to prince |

(Signature)

NAME: SUMAN- KUMAR

DESIGNATION: ASSISTANT- ENGINEER