FIELD INSPECTION REPORT

			And the state of t				
Date of Inspection: 09/01/21			9/01/21	District: End dauparan			
	Division: Rexaut		miles in the manufacture of the second section of the section of the second section of the section o	Length (km): /3/4			Million
N	ime	of the Road: A	nandsegat +	o Gadiyani Tolo	-	angles of embranes	
Se	hen	ne/Programme:	MAINTENANCE	MOGSYCCENT	man man rom	and the second second	n-children
Pa	cka	ge No.:	and a second sec	Road Id No .: 317	100	0125	8
		of the Project:	Ongoing/Completed/	Under Maintenance		10127	
Wo	rk	is a case of:	New Connectivity/Up	gradation/ Maintenance	prof management	The state of the same of the s	
SL	No.		Parameters to b	The second secon	-	Rema	rke
	١.	Pavement	The second secon		William Andrews	200,110	
3)	Road Junction of	condition			\s /U	
b)	Condition of Su	rfacing			vs/U	
С)	Riding Quality				√S/U	
d)		Road Camber				SIU	
c)		Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.					
I)			Pavement)	-	Yes/No	\dashv	
g)		Compaction of fla	nk/slope & raincuts if a	nny		Yes/No	\dashv
2.		Cross Drainage					j
a)	- (Condition of head	walls in Hume pipe cul	verts including its painting		S/SRI/U	
b)		Condition of Abutment & Wing walls, Clab in D.C.				S/SRI/U	-
c)		Condition of railings/slab/approach for Bridges N.A. S/SRI/U					1
3.		oad Furniture			<u> </u>	7010/0	
a)	W sto	hether sign boar ones/Pavement roa	ds/informatory/cautiona d markings are provide	nry Board/km & 200m d and maintained	A	es/No	
4.	Co	mpliance History	1				
1)	Sta	lus of ATR's & an	y others		N-1	4.	
				The second secon		- 1	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	5'
Unsatisfactory (U)	

(Signature)

NAME: Mithilish Kumar Sensol DESIGNATION: Juneof Engineer, Raxaul