

FIELD INSPECTION REPORT

Date of Inspection :	12.1.2021	District:	Aurangabad
Division :	Aurangabad	Length/(km):	1.11 KM
Name of the Road:	L 071 to Keshuti Lapur		
Scheme/Programme:	MAINTENANCE	PMGSY	
Package No.:	BR-07K-582	Road ID No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S U
b)	Condition of Surfacing	✓ S U
c)	Riding Quality	✓ S U
d)	Road Camber	✓ S U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI/NA
c)	Condition of railings/slab/approach for Bridges	S SRI/NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m. ✓ S No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

- ① culvert parapet Not painted
- ② 200 m stone Not found
- ③ KM Stone Not painted

(Signature)

NAME:

Rajendra Prasad Kharwar
A. E. Aurangabad