

FIELD INSPECTION REPORT

| Date of Inspection: <u>→ 11/12/2020</u> | | District: <u>Sikar</u> |
|---|--|------------------------|
| Division: <u>Maharajganj</u> | Length(km): <u>4.050 km</u> | |
| Name of the Road: <u>Madaripur to Lark</u> | | |
| Scheme/Programme: <u>MAINTENANCE</u> | | |
| Package No. <u>BR-34R-338</u> | Road Id No: | |
| Status Of the Project: <u>Ongoing/Completed/Under Maintenance</u> | | |
| Work is a case of: <u>New Connectivity/Up Gradation/Maintenance</u> | | |
| SL.No. | Parameter to be checked | Remarks |
| 1 | Pavement | |
| a) | Road Junction Condition | <u>S/U</u> |
| b) | Condition of Surfacing | <u>S/U</u> |
| c) | Riding Quality | <u>S/U</u> |
| d) | Road camber | <u>S/U</u> |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavements | <u>Yes/No</u> |
| f) | Contraction joints provided or not(CC Pavements) | <u>Yes/No</u> |
| g) | Compaction of flank/slope&rain cuts if any | <u>Yes/No</u> |
| 2 | Cross Drainage | |
| a) | Condition of Head wall in Hume Pipe culverts including its painting | <u>S/SRI/U</u> |
| b) | Condition of abutment & wing wall, slab in RCC Culvert | <u>S/SRI/U</u> |
| c) | Condition of Railings/slab/approach for bridges | <u>S/SRI/U</u> |
| 3 | Road Furniture | |
| a) | Whether Sign boards/informatory/Cautionary board/K.M& 200 mtr.stones/Pavements Road markings are provided and maintained | <u>Yes/No</u> |
| 4 | Compliance History | |
| a) | Status Of ATR,s & any others | <u>N/A</u> |

Overall Rating

| | |
|---|----------|
| Satisfactory(S) | |
| Satisfactory but requires Improvement (SRI) | <u>U</u> |
| Unsatisfactory(U) | |

AP Kumar

NAME:

Designation

AP Kumar
(Signature) 11/12/2020