

FIELD INSPECTION REPORT

Date of Inspection : 04.01.2021
 Division : Beland
 District : Sidamahi
 Name of the Road : Ramashanker Baidya house to balan tola & Jangana Poth
 Length (km): 0.420 km
 Scheme/Programme: MAINTENANCE (RTSNY) near Jagdish P.S.
 Package No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Road Id No.:
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in R.C.C culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	"SRP"
Unsatisfactory (U)	—

Vikas
 (Signature)

NAME: VIKAS KUMAR