## FIELD INSPECTION REPORT

Date of Inspection: 15.1.2021 District: w-Chamberson				
Division: R-W.D. Beltin Length (km): 1.5				
Name of	the Road: Lo	zk sywa tulo	1 Pitchto Kroma Tula Via	Pokhra
Scheme/	Programme:	MAINTENANCE		
Package	Language programmer and the contract of the co		Road Id No.: 31 60 88 00 21	1
Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance				
SI. No.	Net transactions of the east	Parameters to	De checked	Remarks
i i			The same of the first and the same of the	Windship Co.
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2,	Cross Draina	g <b>c</b>	Approximation of the second	
3)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnitu	re		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance I	listory		CONTRACTOR AND
a)		's & any others		NO

Overall	Rating
---------	--------

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Restrotion Brown a Roughverdien PA STON.

DESIGNATION: J.E 7A-E

: