

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Prabhakar

2 Name of Block/Road :- improvement of Baluaka temple clowk to peo more
Dhorki Road (Bochaha)

(A) For Road: ✓

1. Damage Location/Chainage :- 0.100km, 0.500km, 0.950km, 1.20km, 2.20km, 2.80km, 3.5km.
2. Damage Length :- 432.90m (0.4329 km)
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.432km (0.4329 km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

CE
PWD Works Division
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Improvement of Baluaha Temple Chowk to REO More Dhanuki Road
District Muzaffarpur
Block Bochaha
Division Muzaffarpur East-2
Length of Road (in Km) 4.400 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	4.720
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	4.720
TOTAL COST OF PROJECT IN LACS =		4.720

SAY 4.72 Lac.

Santosh Kumar
20/11/2020

JE
20/11/2020

RWD

AE
20/11/2020

AE
RWD

EE
20/11/2020

RWD

Technically Approved for Rs 4.72 Lac.
(Rupees four Lac. seventy two thousand only.)

SE
4.72
RWD work circle
muzaffarpur.