## FIELD INSPECTION REPORT

				With the Party of	
Date of Inspection: 05 Por 1001 District: W. Chambarar			2		
			Length (km): 1.10 10.1		
Division	109 shar				
Name of the Road: PMSH Rorf to 10 yrmin tolq vig Mukujaji 109 slav Scheme/Programme: MAINTENANCE					
A A A A A A A A A A A A A A A A A A A					
Package No.: MMGLY (General)  Status of the Project: Ongoing/Completed/Under Maintenance ON GOLH Gt  New Connectivity/Up gradation/ Maintenance HEW Connector					
Work is a case of:		A STATE OF THE PERSON NAMED IN COLUMN 2 IN		Connectant	
SP Mo	Eff.		the dischard /4	21.07.17.00 mm	
A.	Pagament				
	Road Junction condition			S/U	
a)				S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			WMin	
e)	Whether tree from detects such aggregates in case of CC Pavement.			Yes/No Yes/No	
f)	Contraction Joints provided or not (CC Pavement)				
g)	Compaction of flank/slope & raincuts if any Yes/No			Yes/No	
4	Cross Brainage				
-	Condition of head walls in Hume pipe culverts including its painting SA			S/SRI/U	
a)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
b)	Condition of railings/slab/approach for Bridges			S/SRI/U	
(c)					
3.	Road Furniture				
a)	Whether sign boards/informatory/cantionary Board/km & 200m yes stones/Pavement road markings are provided and maintained			Yes/No	
4	Compliance History			-	
B)	Status of ATR's & any others				
-/					

Overall Rating

j_	
Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note: work in frogress

(Signature)

NAME; SUNIL QUHAR

designation:  $\mathcal{J} \in$ 

Scanned by CamScanner

£.