Inspection Report for Flood Damage Work

Date :	24.	12	2020	
Date		_		

- 1. Name of PIUs Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
- 2. Name of Block Paroo
- 3. Name of Road/Bridge Tirhut Bandh Dhala to Sohansi Village in Chandkewari panchayat of Paroo Block of Muzaffarpur District With RCC Bridge

A. for Road

- 1. Damage Location/Chainage : 0.300KM to 0.450KM
- 2. Damage Length : 60 M.
- 3. Nature of Damage : Breach of Rend Count with Embolional.
- 4. Details of Restoration Works
 - i. Material being used in Restoration works: Subgrate (Early),
 - ii. Equipments/Tools being used in Restoration Works: Tracker, J. C. B, Roller
 - iii. Procedure taken up in Restoration works: Easta fly in break portion,
 - iv. Restored Length: ___ Lott
- B. for Bridge
- 1. Damage Location/Chainage :
- 2. Damage Length :
- 3. Nature of Damage
- 4. Details of Restoration Works
 - i. Material being used in Restoration works:
 - ii. Equipments/Tools being used in Restoration Works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length:

J.E.

128 1742020

Executive Engineer, R.W.D. Works Division, Muzaffarpur west Signature (Name of Inspector)