

FIELD INSPECTION REPORT

Date of Inspection : 19.01.2024	District: Sonpur
Division : Sonpur	Length (km): 0.320
Name of the Road: Banwaripur Hanuman teela to PMGSY Road	
Scheme/Programme: MAINTENANCE	
Package No.: G.T. S.M.	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SAT
c)	Riding Quality	✓SAT
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

[Signature]
19/1/24
(Signature)

NAME: Vinod Kumar Singh

DESIGNATION: J.C

Darjeeling