

Inspection Report for Flood Damage Work

Date:- 15-1-21

1 Name of PIUs :-

2 Name of Block/Road :-

purnea charle purnea to Chosant ghat via
Bada Bhasi talu


(A) For Road:

1. Damage Location/Chainage :- 1st km
2. Damage Length :- 118.2 mtr
3. Nature of Damage :- Fully road cut
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- concrete
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 118.2 mtr

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)
Executive Engineer
R.W.D. Works Division
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Pukar chawk PMGSY to Ghosaut Ghat Via Bada Bharti Tak

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 2.582 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	34.772
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.523
	GRAND SUB TOTAL	35.294
TOTAL COST OF PROJECT IN LACS =		35.294

Mug
8.1.21
JE
RWD

AS
08/01/21
AE
RWD

9m
8/1/21
EE
RWD

Technically approved for Rs 35.294 lac
(Rupees Thirty five lac twenty nine thousand four hundred only)

SG
16.1.21

RWD none circle
muzaffarpur