Inspection Report for Flood Damage Work

Date:-

15-1.21

1 Name of PIUs: - myaffarbur East 2.

2 Name of Block/Road :-

sugan paleri undendra chardren House to Johan tola

(A) For Road:

1. Damage Location/Chainage :- Tholking

:- 82-0 mm 2. Damage Length

:- Road cutturs. 3. Nature of Damage

4. Details of Restoration Works :-

Material being used in Restoration works:- Ponck bets (i)

Equipment's/Tools being used in Restoration works:- Tseetw (ii)

Procedure taken up in Restoration works: (iii)

:- 82-0m/8 Restored Length (iv)

(B) For Bridge:

1. Damage Location/Chainage

2. Damage Length

3. Nature of Damage

4. Details of Restoration Works :-

Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) Executive Engineer R.W.D. Works Division Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

Sujan Pakri Upendr Chaudhari House to Lohar tola

Muzaffarpur

Minapur

Muzaffarpur East-2

angth of Road (in Km)

1.750 Km

Length of Road (In Km)		AMOUNT (LAKHS)
SI. No.	DESCRIPTION	8.299
1	Jhama metal	0.000
2 .	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	8.299
	GRAND SUB TOTAL	8.299
TOTAL	COST OF PROJECT IN LACS =	

RWD

RWD

RWD

Technically approved for RS 8,30 lae.

(Rubecs Bight lae thirty thousand only)

SE'S'I'S

RWD wome cirale Muzaffarput