Inspection Report for Flood Damage Work

Date:-1 Name of PIUs: - Gyan viblakar 2 Name of Block/Road: - vadia pmasy Road Via, Akhilest ram home to hodivari shir monder (Gaighat) 1. Damage Location/Chainage :- 0.100km, 0.20km, 0.60km, 1.10km; 1.3km (A) For Road: (Lenst = 3,218 km) :- 105.40M (0.1054 Fm) 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works: Material being used in Restoration works:-(i) Equipment's/Tools being used in Restoration works:-(ii) Procedure taken up in Restoration works: 10.1054 km) (iii) :- 0.102 km. Restored Length (iv) % (B) For Bridge: 1. Damage Location/Chainage :-2. Damage Length 3. Nature of Damage 4. Details of Restoration Works: (i) Material being used in Restoration works:-(ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works:-(iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection)

PWD WORK DIVISION
MUZITHORPHY CONT-1

GENERAL ABSTRACT

Name of Road

Vadia PMGSY Road via Aklisesh Ram House to Godiayari Shiv Mandir

District

Muzaffarpur

Block

Gaighat

Division

Muzaffarpur East-2

Length of Road (in Km)

1.561 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	3.518
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	3.518
TOTAL (COST OF PROJECT IN LACS =	3.518

Says 3.52 lac

Je RWD

K. 12120

ΑE

RWD

EE OR II

Technically Approved for B 3.52 Lac (Pupees three lac, fifty two thousand only).

pwp work circle