Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs: - Gyan viblaker

2 Name of Block/Road: - Churning hat to Jarany Chowk take

(A) For Road:

- 1. Damage Location/Chainage :- 0.205 km :- 0.0135 km
- 2. Damage Length

(Lery 1- 1.574 km)

- 3. Nature of Damage
- 4. Details of Restoration Works:
- Material being used in Restoration works:- back bads (i)
- (ii) Equipment's/Tools being used in Restoration works:-
- Procedure taken up in Restoration works: (iii)
- Restored Length (iv)
- :- 0.0135 km

(B) For Bridge: X

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection)

EE

RWD WOOK DIVISION my zaffar bur Eart-L

GENERAL ABSTRACT

Name of Road

churniya Hat to Jarang Chowk Tak

District

Muzaffarpur

Block

Gaighat

Division

Muzaffarpur East-2

Length of Road (in Km)

1.574 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	3.304
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	3.304
TOTAL C	OST OF PROJECT IN LACS =	3.304

Says 3.30 LAC

311212020

JE

RWD

311/2/2

AE

RWD

EE

RWD

Technically Approved for Bs 3.30 tac (Purcey three Lac thisty Housend only.) -

pwp work crocle