Inspection Report for Flood Damage Work

Date:-1 Name of PIUs: - Gigan vibhakar 2 Name of Block/Road: mahraul Berrai Tolar to mminsy (A) For Road: 1. Damage Location/Chainage :- 0 5000 km 2. Damage Length :- 0.20 km 3. Nature of Damage 4. Details of Restoration Works: Material being used in Restoration works: - Brick Sall stocal sand (i) Equipment's/Tools being used in Restoration works:- Tools (ii) Procedure taken up in Restoration works: (iii) (iv) Restored Length :- 0-201cm (B) For Bridge: 1. Damage Location/Chainage 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works: (i) Material being used in Restoration works:-(ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works:-(iv) Restored Length

Signature of JE/AE/EE

Signature Signature

(Name of Inspection)

EE

RWD MUZABBAYPUY East-1

GENERAL ABSTRACT Mahraul Berai Tola to MMGSY Name of Road Muzaffarpur District Katra Block Muzaffarpur East-2 Division Length of Road (in Km) 0.600 Km DESCRIPTION SI. No. Earthwork Jhama metal 2 Sand Filling 3

ory 7.66 lac

AMOUNT (LAKHS)

0.000

3.706

3.954

0.000

0.000

7.660

7.660

11/1/21 JE

Sand bag

GRAND SUB TOTAL

TOTAL COST OF PROJECT IN LACS =

H.P.

4

5

RWD

AE 11.1201

RWD

EE

Technically approved for RS 7.66 lac (seven lac sixty six thousand only)

RND WORK CHOLLE