

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- prasad mmnsy path to puraina vinda Rajee garh

### (A) For Road:

1. Damage Location/Chainage :- 0.650 km, 0.730 km, 0.915
2. Damage Length :- 0.130 km
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- Bone balls
  - (ii) Equipment's/Tools being used in Restoration works:- Tractor
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.130 km

### (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

Signature

(Name of Inspection)


EE

RWD muzaffarpur GCSA-1


## GENERAL ABSTRACT

Name of Road Parsad MMGSY Path to Puraina Vinda Ray Ke Ghar  
District Muzaffarpur  
Block Minapur  
Division Muzaffarpur East-2  
Length of Road (in Km) 1.324 Km


Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	30.973
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	30.973
TOTAL COST OF PROJECT IN LACS =		30.973

  
11/1/21


JE  
RWD

  
11/01/21

AE  
RWD

  
11/1/21  
EE  
RWD

Technically approved for Rs 30.973 lac  
(Rupees thirty lac ninety seven thousand three hundred  
only)

  
SE 13.1.21

RWD work circle  
muzaffarpur