

Inspection Report For Flood Damage Work

| - | | 11 | | |
|----|---|----|---|----|
| 13 | a | ٠ | | Ç. |
| _ | ч | | = | |

Cappalgani - 2

2 Name of Block/Road: Balkenthour / PMBSY Road se Late Tolq

For Road

1 Damage Location / Chainage: 100 m to 345 m

2 Damage Length:

3 Nature of Damage:

Heavy Rain / Flood

4 Details of Restroration Works:

Material being used in Restoration Works:

Botch Bats

Il Equipments / Tools being used in Restoration Works: 100 , Tractor, Troli, Belehy, Should

iii Procedure taken up in Restoration Works:

iv Restored Length:

1870

B For Bridge

- 1 Damage Location / Chainage:
- 2 Damage Length:
- 3 Nature of Damage:
- 4 Details of Restroration Works:
 - i. Material being used in Restoration Works:
 - ii Equipments / Tools being used in Restoration Works:
 - iii Procedure taken up in Restoration Works:
 - iv Restored Length:

(Name of Inspector)





ग्रामीण कार्त विभाग

Rural Works Department, Govt. of Bihar

FLOOD DAMAGED REPAIR (F.D.R.)

STATE :- BIHAR

DISTRICT :- GOPALGANJ

BLOCK :- BAIKUNTHPUR

PMGSY Road Se Lala Tola

ESTIMATED COST - RS.

980900.00

SUBMITTED BY :-

EXECUTIVE ENGINEER RWD (W) DIVISION GOPALGANJ-2

Report

Name of Work

Motorable work of PMGSY Road Se Lala Tola

Estimated Cost

980900.00 •

Total length of Road

0.835 km

Description :- The present estimate has been farmed under the supervision of Assistant engineer in accordance with the order of Executive Engineer, RWD, WD Gopalganj-2, letter No. - 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transporation has been obstructed. The immediate motorable work is necessary in public interest. Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. In the context of post flood scenario there is still the flow of water which prevails through the damaged part of the road.

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.

Detailed Estimate For Motorable Work in Road from PMGSY Road Se Lala Tola damaged due to Heavy rain/flood for year 2020-2021

| Items | No. | L (M.) | W (M.) | D (M.) | Qty. | Unit | Rate | Amount |
|---|-----|--------|--------|--------|--------|------|---------------------|-------------------------|
| Providing brick bats billed in ditches including all cost of labour & material with all complete job. | | | | | | | | |
| CH - 100 M to 345 M | 1 | 7.00 | 1.50 | 0.60 | 6.30 | МЗ | | |
| | 1 | 5.00 | 0.60 | 0.40 | 1.20 | M3 | | |
| | 1 | 22.00 | 2.00 | 1.00 | 44.00 | МЗ | | |
| | 1 | 8.00 | 1.00 | 0.60 | 4.80 | M3 | | |
| | 1 | 23.00 | 1.00 | 1.05 | 24.15 | МЗ | | |
| | 1 | 29.00 | 1.35 | 2.40 | 93.96 | M3 | | |
| | 1 | 18.00 | 1.30 | 2.25 | 52.65 | M3 | | |
| | 1 | 30.00 | 1.60 | 1.00 | 48.00 | М3 | | |
| | 1 | 25.00 | 2.00 | 0.70 | 35.00 | M3 | | |
| | 1 | 20.00 | 1.50 | 3,00 | 90.00 | МЗ | | |
| Less for H.P. | 0 | 1.23 | 1.23 | 0.95 | 0.00 | МЗ | 2412-11 | 9649892 |
| | | | | | 400.06 | M3 | 2427.65 | - 9712 05.66 |
| Providing & laying 1000 MM Dia NP3 Hume Pipe in single row -do-do- complete job. | 0 | 2.50 | | | 0.00 | м | 2783-13 -4159:56 | 0.00 |
| | | | | | | | | 971205.66 |
| Add 1 % Contigency | | | | 2 | | | | 969712.06 |
| | | | | | 974689 | ~_ | Total | 980917.72 |
| | | | | | 1 1/2 | | Say | 980900:00 |

974639 =

13.09.2090

E.E.

E.E.

tor 14 9.746 lac (dupice)

Superintending Enginee.

Superintending Enginee.

Superintending Enginee.

Superintending Enginee.

Superintending Enginee.

Superintending Enginee.