

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- Janta kanta PMWSY Road to kanta haziJan tola.

(A) For Road: ✓

1. Damage Location/Chainage :-

0.450km, 0.630km, 0.815km, 1.15km, 2.25km, 2.80km, 3.25km, 3.55km

2. Damage Length :-

645.7 M (0.6457 km)

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:- brick bats

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :- 0.6457 km

(Length = 410 km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE


RWD WORK DIVISION
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Janta Kanta PMGSY Road to Kanta Harijan Tola
District Muzaffarpur
Block Gaighat
Division Muzaffarpur East-2
Length of Road (in Km) 4.000 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	19.156
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	19.156
TOTAL COST OF PROJECT IN LACS =		19.156


JE
RWD


AE
RWD


EE
RWD

Technically approved for Rs 19.156 lac

(Rupees Nineteen lac fifteen thousand six hundred only)


अधीक्षक अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर