

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *Gyan Vihar*

2 Name of Block/Road :- *PMGSY Ram Chandra Prasad House to water wage*

Bandh via Shatrudhan Thakur House

✓ (A) For Road:

1. Damage Location/Chainage :- *4600, 607, 660 and many places*
2. Damage Length :- *76.80m*
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- *Brick bats*
 - (ii) Equipment's/Tools being used in Restoration works:- *Tractor*
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :-

✓ (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

[Signature]
15.1.21
Signature


(Name of Inspection)
Executive Engineer
R.W.D. Works Division
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road PMGSY Ram Chandra Prasad House to Water Wage Bandh Via Shatradhan Thakur House
District Muzaffarpur
Block Minapur
Division Muzaffarpur East-2
Length of Road (in Km) 1.120 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	4.102
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	4.102
TOTAL COST OF PROJECT IN LACS =		4.102


say 4.10 lac


07.01.2021

JE
RWD




AE
RWD



EE
RWD

Technically approved for Rs 4.10 lac
(Rupees four lac ten thousand only)


16.1.21
SE

RWD zone circle
muzaffarpur