Inspection Report for Flood Damage Work

Date:-

Gyan Vistanes 1 Name of PIUs:-

2 Name of Block/Road:-

PMOSY Road to sans Ram

(A) For Road:

- 1. Damage Location/Chainage :- ch 97 120 65147
 2. Damage Length :- 3/1002

3. Nature of Damage

- 4. Details of Restoration Works:
- Material being used in Restoration works:- Briens as (i)
- Equipment's/Tools being used in Restoration works:- Tracks (ii)
- Procedure taken up in Restoration works: (iii)
- Restored Length (iv)

:- 31.00

(B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
 - :-
- 4. Details of Restoration Works:
- Material being used in Restoration works:-(i)
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE (Name of Inspection) Executive Engineer R.W.D. Works Division Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

Pmgsy Road to Saroj Ram

District

Muzaffarpur

Block

Minapur

Muzaffarpur East-2

1	Muzanarpur 2001	0.200
Division	- 4 (in Km)	AMOUNT (LAKHS)
Length of	Road (in Km)	1.510
SI. No.	DESCRIPTION	0.000
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	1.510
4	H.P.	1.510
	GRAND SUB TOTAL	
TOTAL C	COST OF PROJECT IN LACS =	Say 1.5

say 1.51 lac

JΕ

RWD

RWD

RWD

0.200 Km

Technically approved for RS 1-51 lac.

(Rupees one lac fifty one thousand only)

fun work circle myzosffaspurk