

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vishwak

2 Name of Block/Road :- Raghopur PMGSY Road to Ramshera Rai House take

(A) For Road:

1. Damage Location/Chainage :- 160, -- 325, -- 577, 515 -- 1045^m with many places
2. Damage Length :- 397.50m
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Bricks/bags
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor/Truck
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 397.50m

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)
Executive Engineer
R.W.D. Works Division
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Raghupur PMGSY Road to Ramsherst Rai House Tak

District Muzaffarpur


Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 1.074 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	21.991
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	21.991
TOTAL COST OF PROJECT IN LACS =		21.991

say 21.99 lac


07.01.2021

JE
RWD



AE
RWD



EE
RWD

Technically approved for Rs 21.99 lac
(Rupees Twenty one lac nineteen nine thousand only)


12.1.21
SE

RWD work circle
muzaffarpur