Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs:-2 Name of Block/Road :-Cryan Vittakar

Byahaman Chowle to Brahaman polear Hote mag or

Cholasthur House

(A) For Road:

1. Damage Location/Chainage 2. Damage Length :- ch 20, 100, 510, 1120, 2335 and many place

3. Nature of Damage

4. Details of Restoration Works :-

Material being used in Restoration works:- Brick Sels (ii) (iii)

Equipment's/Tools being used in Restoration works:- Track Procedure taken up in Restoration works: (iv)

(B) For Bridge:

1. Damage Location/Chainage

2. Damage Length

3. Nature of Damage

4. Details of Restoration Works:

Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) Executive Engineer R.W.D. Works Division Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

Brahaman Chowk to Brahaman Poker Hote Majoor Gohasipur House

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

2,484 Km

Lengu	•	2.404 11
SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	15.389
	Sand Filling	0.000
		0.000
3	Sand bag	0.000
4	H.P.	
	GRAND SUB TOTAL	15.389
	OCT OF PROJECT IN LACCE	15.389
TOTAL C	OST OF PROJECT IN LACS =	

Suy 15.39 lac

107.01.2021 NOTH

• ,

ΑE

RWD

RWD

Technically approved for RS 15-39 lac.
(Rupees sitteen lac thirty more thousand only)

SE

RWD WORL CHOCLE