

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme: Ambedkar Pur Chowk to Janisb Path

Hazards: Flood/Rain Flood

Division: Benipur District: Darbhanga Actual Length (in km): 3.90

Damage Length (in km): 2.10 Damages Location/Chainage: 1350 - 2130 and 2280 - 3900m

Name of Scheme/Programme: FDR 3054

Status of Project: Under Agreement/Out of Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks: (S/U)

1. Pavement (BT/CC) BT

a) Condition of Surfacing S

Description of observation: GSB Gr I Length 1320m
WBM Gr III Length 1850m

b) Adequate Thickness of pavement layers constructed

Description of observation: Thickness taken at 3300m
GSB Gr I 100mm
WBM Gr III 75mm M.S. not done

c) Quality of Construction Material Used S

Description of observation:

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. N/A

Description of observation:

e) Compaction of flanks/ slope & raincuts S

Description of observation:

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges S

Description of observation of CD works:

Remark if any: GSB Gr I and WBM Gr III in length 250m work not done
M.S.S. work not done

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer: Bindu Raju
Executive Engineer

Designation: **RWD, Regional Laboratory**
Darbhanga

DA 10/7/21
A.E.

Signature
10/7/21