

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल बेनीपट्टी ।

पत्रांक 1167 3170

दिनांक 08.07.2018

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेनीपट्टी ।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी – सह – सचिव,
बिहार ग्रामीण पथ विकास अभिकरण,
ग्रामीण कार्य विभाग,
बिहार, पटना ।

विषय:-

शीर्ष NEW MAINTENANCE POLICY – 2018 (MR – 3054) में आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में कहना है शीर्ष NEW MAINTENANCE POLICY – 2018 (MR – 3054) अन्तर्गत पथ में संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय ताक संवेदक का भुगतान किया जा सके।

अनु०:-

1. अधियाचना प्रमाण पत्र 1 पृष्ठ में ।
2. उपयोगिता प्रमाण पत्र एक प्रति ।

विश्वासभाजन

मृ० ४५८
6-7-2018
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेनीपट्टी ।

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilisation Certificate Upto the month of 30 June 2021

New Maintenance policy - 2018

PIU – Executive Engineer, R.W.D (W) Division, Benipatti

SL. No	Name of Gen.heme	Sanction No. & Date with Amount (In Rs. lacs)	Amount Received (In Rs. lacs)	Particulars
1	Construction of Rural roads under New maintenance policy - 2018	Authorization letter No. 34 dt-04.06.2021 Rs.13.78968	704.30751	Certified that out of Rs.704.30751 Lakh received during the years up to 2021-22 (30 June 2021) in favour of Ex. Engineer, RWD (W) Division Benipatti, Madhubani, Bihar, a sum of Rs. 703.48403 Lakh has been utilized for the purpose of New maintenance policy-2018 as given in the margin for which the balance of Rs 0.82348 Lakh remaining unutilized at the end of the period under.

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- I. Works have been supervised by Executive Engineer/Superintending Engineer.
- II. Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- III. Construction materials have been tested.
- IV. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- V. All other codal formalities have been observed.

3. Physical Progress achieved:-

- I. Construction of Road Works.
- II. Construction of CD Works.

Om Prakash
Sr.D.A.O
R.W.D (W) Division
Benipatti

27/7/21
Executive Engineer
R.W.D (W) Division
Benipatti

f Division :- Benipatti

Format of Requisition under Head New Maintenance policy - 2018 (MR- 3054) for the month of July - 2021

Name of road	Project ID as per MIS	Administrative Approval No & Date (AA) Letter No & Date	Administrative Approval (AA)	Agreement Amount (in Lakh)		Initial Rectification with Surface Renewal (In Lakh)	5 Year Routine Maintenance (In Lakh)	Agreement & Date as per Agreement	Date of Completion as per Agreement	Actual Date of Completion	Value of HSI (in mm/mm)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Alotted Amount (In Lakh)	up-to-date expenditure as against work done (in Lakh)	Requisition Remarks
				Length (in km)	Amount of (in lakh)											
3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
Bankattai to Canguli	3.191E+10	24/06/2019	1859	2.510	81.39990	51.55049	20.86945	71MBD/19/20 25/01/2020	24/01/2021	—	2630	25	5	39.06883	38.85150	13.97220 BT Work Completed
Uchaitai - Sonrai	3.191E+10	24/06/2019	1859	4.200	133.05540	88.63191	33.06953	71MBD/19/20 25/01/2020	24/01/2021	—	3050	25	5	70.68686	70.68686	14.48108 BT Work Completed
Total				6.710	214.455	140.18240	53.93898			—	5680	50	10	109.75569	109.53836	28.45328

Sr.D.A.O
R.W.D(W)Div. Benipatti

21/7/2021
Executive Engineer
R.W.D(W)Div. Benipatti

2nd on A/C ~~Bill~~ Bill.

8

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W :-	Maint. of Road & C.D work				
	MR - N/19-20-01	for the road			
	Bankatta to Ganguly				
Agency :-	Sri Gobind Tha				
Agr No. :-	71 MBD/19-20				
D.O.S. :-	25-01-2020				
D.O.C. :-	24-01-2020				

Record Entry.

① clearing & grubbing Road Land
-- all Comp job --- SDEFI.

up to date.

$$2 \times 25 \times 100 \times \frac{1.4 + 1.60}{2} = 7500 \text{ m}^3$$

$$2 \times 10.40 \times \frac{1.4 + 1.60}{2} = 30.40$$

$$\underline{\quad \quad \quad 7530 \text{ m}^3}$$

② P/L WBH gr-III with app.
quality of matt -- all
Comp job --- SDEFI

$$2 \times 15 \times 1.50 \times 0.075 = 3.375 \text{ m}^3$$

$$2 \times 5 \times 1.25 \times 0.075 = 0.937 \text{ m}^3$$

$$2 \times 2.5 \times 2.10 \times 0.075 = 0.75$$

$$\underline{\quad \quad \quad 5.062 \text{ m}^3}$$

③ P/A Prime Coat -- all
Comp job --- SDEFI.

$$2 \times 7.70 \times 2.10 = 33.18 \text{ m}^2$$

$$2 \times 2.60 = 5.20 \text{ m}^2$$

$$\underline{\quad \quad \quad 38.38 \text{ m}^2}$$

Abstract of Cost

11

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① clearing & grubbing Rd land					
qUTMB P-8	0.75 Hect				
@ ₹ 4946.70	—	—	—	—	37123.00
② Const. of subgrade & E. shoulder					
qUTMB P-10	1347.50 M ³				
@ ₹ 176.75	—	—	—	—	238524.00
③ Const. of GSB	—	—	—	—	
qUTMB P-2	24.32 M ³				
@ ₹ 3236.80	—	—	—	—	78719.00
④ P/L wBM gr-III					
qUTMB P-2	22.48 M ³				
" P-8	5.062 M ³				
	27.542 M ³				
@ ₹ 4008.97	—	—	—	—	110415.00
⑤ P/A Prime coat	—	—	—	—	
qUTMB P-3	328.87 M ²				
" P-8	38.38 "				
	367.25 M ²				
@ ₹ 41.24	—	—	—	—	15145.00
⑥ Patch work over wBM with Mix seal surfacing					
qUTMB P-4	2341.46 M ²				
" P-8	38.72 M ²				
limit to	2380.18 M ²				
	2376.66 M ²				
@ ₹ 212.71	—	—	—	—	505539.00
⑦ P/A tack coat	—	—	—	—	
qUTMB P-4	11296.46 M ²				
" P-9	697.09 M ²				
	11993.55 M ²				

Sch. XLV—Form No. 134

14

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
less Power. Pay			BF	M	5304103.00
				M	3885150.00
				M	1418953.00

Handi channel
20/04/21
T.E. MG

up to date Matt. statement

S/M - 467.28 M³

C/S - 5.83 M³

Filler - 10.50 MT

EM SS1 - 0.312 MT

EM RS1 - 3.267 MT
EW - 1349.50 M³

Bit - 33.034 MT

Handi
20/04/21

Quality control report should be
collected by office from The Agency.

Handi
20/04/21
T.E.