

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: <u>Laxmi Pur Halt To Gauri Meran Road Par Border via Laxmi Pur</u>			
Hazards	Flood/Rain <u>Flood</u>		
Division: <u>Madhubani</u>	District: <u>Madhubani</u>	Actual Length (in km): <u>1.850</u>	
Damage Length (in km): <u>0.150</u>	Damages Location/Chainage: <u>200m to 150m</u>		
Name of Scheme/Programme: <u>Flood F.D.R 3054</u>			
Status of Project: <u>Under Agreement/Out of Agreement</u>			
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S)
1.	Pavement (BT/CC) <u>BT</u>		<u>S</u>
a)	Condition of Surfacing		
Description of observation : <u>Pot - patch work done</u>			

b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation : <u>GSB Gr I - 150mm</u> <u>WBM Gr II - 75mm</u> <u>MSS - 20mm</u>		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation :		

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>S</u>
Description of observation :		

e)	Compaction of flanks/ slope & raincuts	<u>S</u>
Description of observation :		

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>N.A</u>
b)	Condition of Vent Clearance	<u>N.A</u>
c)	Condition of railings/Slab approach for Bridges	<u>N.A</u>
Description of observation of CD works :		

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U) S

Young Engineer

Designation

Bimal Rajak
Executive Engineer
R.W.D
Regional Lab, Darrbhanga

[Signature]
20/03/21
A.E.

[Signature]
20/03/21
S.D.O.