

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 30/7/21		District: Chapra Saran
Division : Chapra-2		Length (km): 1.066
Name of the Road: LSI-TO2 to Kesari CVR 35		
Scheme/Programme: PMGSY		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:-		
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	} NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	
Observation Remarks:-		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	<b>Compliance History</b>	—
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

Designature:-

Bindu Rajak  
Executive Engineer  
R.W.D.  
Regional Lab. Darbhanga

30/7/21  
A.E.

(Signature)

30/7/21