GENERAL ABSTRACT

Name of Road

Ramequbal Singh chowk to Dhunia Tola Dakhin Tola Tak

District

Muzaffarpur

Block

Bochaha

Division

Muzaffarpur East-2

Length of Road (in Km)

2.120 Km

| | | AMOUNT (LAKHS) |
|---------|---------------------------|----------------|
| SI. No. | DESCRIPTION | 9.220 |
| 1 | Jhama metal | 0.000 |
| 2 | Sand Filling | 0.000 |
| 3 | Sand bag | 0.000 |
| 4 | Bamboo Piles | 9.220 |
| | GRAND SUB TOTAL | 9.220 |
| TOTAL C | COST OF PROJECT IN LACS = | |

3043 9.22 Jac

RWD

RWD

Technically Approved for Ps 9:22 lac (prupees mine lac, twenty two thousand only).

> BOD most circle muzaffar pur

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs: - Gyan viblakar

2 Name of Block/Road: - Ramerybal singl clook to dhyning tola dakkin tola.

(A) For Road:

:- 0.400m, 0.500m, 0.700m, 0.950, 1.50m, 1. Damage Location/Chainage

:- 900 m 0.4144km 2. Damage Length 1,80m, 210m

3. Nature of Damage

4. Details of Restoration Works:

(Length = 2.7 20 mg) Material being used in Restoration works:- Brick bouts.

Equipment's/Tools being used in Restoration works:-(ii)

(Bochata)

Procedure taken up in Restoration works: (iii)

(iv) Restored Length :- 0.4144 km

(B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- Material being used in Restoration works:-(i)
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection)

RWD work DIVISion. myzafferbur East-L