

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, समस्तीपुर

पत्रांक 1201

दिनांक 09.06.2021

प्रेषक:-

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, समस्तीपुर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:-

महाशय,


शीर्ष New Maintenance Policy-2018 मद में आवंटन उपलब्ध कराने के संबंध में।


उपर्युक्त विषयक शीर्ष New Maintenance Policy-2018 मद अन्तर्गत व्यय हेतु
विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजी जा रही है।

अतः अनुरोध है कि संलग्न अधियाचना पत्र के अनुसार आवंटन उपलब्ध कराने की
कृपा की जाये।

अनु0-यथोक्त।

विश्वासभाजन


9.6.21

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, समस्तीपुर

09.06.21

FROM GFR 19-A

(See Government of India's Division (I) below Rule- 150)

Form of Utilization Certificate upto 31.05.2021

PIU- E.E., R.W.D. Works Division, Samastipur

S.N.	Name of Scheme	Sanction No.& Date	Amount Received	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	Secretary cum Empowered Officer BRRDA Bihar Patna vide upto	152836088.00	Certified that out of Rs.152836088.00 received upto 31.05.2021 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.143462430.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margine for which it was sanctioned and that the balance of Rs. 9373658.00 remaining unutilized at the end of period under report.
			15,28,36,088.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for the which it was sanctioned.

Kind of Checks exercised:-

- i Works have been supervised by Executive/Superintending engineer.
- ii Periodical inspection has been conducted by Executive/Superintending engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.

**Sr. Divisional Account Officer
R.W.D (W) Division Samastipur**


Executive Engineer
Works Division Samastipur
Rural Works Department

Rw
09.06.21

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

R.R.D. Works Division : Samastipur																		
Sl No	Package No	Project ID as per MIS	Name of Road	Administrative Approval (AA) Letter No & Date	Length (Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance	Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bituminous Layer (in MM)	Value of Bituminous Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up to date Expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/SASA/MT/190008	32010102071	SH Rudauli Chowk se Laguniya	2173 & 06.07.2019	2.80	83.9454	44.502876	24.18246	08(MBD) 2019-20 03.01.2020	09.05.2021	OnGoing	3524	25	5.12	0	0	44.503	BT Completed
2	RM/SASA/MT/190012	NEA22000585	T03 - SHIVSINGPUR	2173/ 07.06.19	1.20	31.55	27.455	11.74023	14(MBD) 2019-20/ 02.03.2020	07.10.2020	Complete	3411.83	25	5.2	22.566	22.566	4.797	BT Complete
Total						115.49540	71.95788	35.92269							22.566	22.566	49.300	


- 1 Signed Hand Copy and Soft Copy (In Excel) of recorded IRI is enclosed.
2 Up-to-date Physical Progress has been uploaded in MIS

Sd. Divisional Account Officer
R.W.D (W) Division Samastipur

[Signature]
07/06/2021
SE

[Signature]
Executive Engineer
RWD (W) Div. Samastipur
09.06.21

File :D:\bump\Integrated\RWd div Samastipur\SH ruddauli chowk se.xlsx Section No. :92. Egn test
 Name of Customer :Sona intracon Pvt. Ltd. Name of Work/ Road :SH Ruddauli chowk se Laguniya. Lab Job number



[Signature]
 01/06/2021
 JE

[Signature]
 01/06/2021
 AC

[Signature]
 Executive Engineer
 R. W. D. Works Division
 01/06/21

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event			
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD						
1/6/21	10:28:7	92	0.1	490	0	1900	2698 G		25.82199	85.77781	Normal		$Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$	
1/6/21	10:28:7	92	0.1	440	20.2	3400	4130 A		25.82211	85.776835	Curve		X = 5700	
1/6/21	10:29:0	92	0.1	360	10.1	2600	3222 G		25.82251	85.775958	Normal		Y = 6607	
1/6/21	10:29:18	92	0.1	420	10.1	3500	4103 A		25.82272	85.77502	Curve			
1/6/21	10:29:18	92	0.1	410	10.1	3400	4090 A		25.82334	85.774628	Curve		(R) RURAL ROAD	
1/6/21	10:30:0	92	0.1	430	10.1	3500	4017 A		25.82416	85.774343	Curve		Good	
1/6/21	10:30:0	92	0.1	480	10.1	2600	3285 G		25.82473	85.773602	Normal		Average	
1/6/21	10:30:28	92	0.1	520	10.1	2400	3239 G		25.82486	85.772608	Normal		4001-5000	
1/6/21	10:31:3	92	0.1	420	10.1	3100	3803 G		25.82498	85.771565	Breaker		Poor	
1/6/21	10:31:3	92	0.1	390	10.1	1900	2562 G		25.82518	85.770673	Normal			
1/6/21	10:32:0	92	0.1	430	10.1	2300	3117 G		25.82546	85.769697	Normal			
1/6/21	10:32:14	92	0.1	400	20.2	3100	3876 G		25.82568	85.76872	Normal			
1/6/21	10:33:0	92	0.1	490	10.1	3500	4098 A		25.8257	85.767727	Curve			
1/6/21	10:33:24	92	0.1	350	10.1	2500	3108 G		25.8252	85.767037	Normal			
1/6/21	10:33:24	92	0.1	440	10.1	2400	3130 G		25.82524	85.76606	Normal			
1/6/21	10:34:0	92	0.1	540	20.2	3400	3966 G		25.82516	85.76505	Normal			
1/6/21	10:34:0	92	0.1	440	10.1	1900	2730 G		25.82507	85.764057	Normal			
1/6/21	10:34:0	92	0.1	500	20.2	2600	3312 G		25.82502	85.763097	Normal			
1/6/21	10:34:35	92	0.1	380	10.1	3400	4019 A		25.82494	85.762172	Speed			
1/6/21	10:35:0	92	0.1	340	20.2	3400	3994 G		25.82497	85.761143	Breaker			
1/6/21	10:35:9	92	0.1	340	20.2	3400	3994 G		25.825	85.76015	Normal			
1/6/21	10:35:9	92	0.1	350	20.2	2500	3108 G		25.82504	85.759123	Normal			
1/6/21	10:35:45	92	0.1	420	20.2	2200	2903 G		25.8252	85.758198	Normal			
1/6/21	10:36:0	92	0.1	330	10.1	3300	3881 G		25.82538	85.757222	Normal			
1/6/21	10:36:20	92	0.1	490	20.2	2900	3698 G		25.8253	85.756295	Normal			
1/6/21	10:37:0	92	0.1	480	10.1	3400	4085 A		25.82579	85.755487	Curve			
1/6/21	10:37:30	92	0.1	470	20.2	1700	2471 G		25.82641	85.754763	Normal			
1/6/21	10:38:6	92	0.1	570	10.1	3500	4057 G		25.82703	85.753988	Speed			
											Breaker			

at Reading 4000 for 4000 of 342 at 10.1, Speed Breaker at Curve 45.5201 at 10.1

Don't
01/06/2021
JE

01/06/2021
AE

Executive Engineer
R. V. D. Works Division
P. O. Mahalingapuram