

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: Radhe madhe Dakshin Tola To Radhe madhe South Tola middle school.		
Hazards	Flood/Rain	
Division : Manihari	District: Katihar	Actual Length (in km): 4.508
Damage Length (in km): 3.108	Damages Location/Chainage: -	
Name of Scheme/Programme:	FDR	
Status of Project:	Under Agreement/Out of Agreement - out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S
Description of observation :		
BT work		
b)	Adequate Thickness of pavement layers constructed	
Description of observation :		
Mix seal surface - satisfactory		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	S
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	S
Description of observation :		
In partial length, Accumulation of water in both side of road is existing due to rainy season & its own topography i.e. low land Area.		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	-
b)	Condition of Vent Clearance	-
C)	Condition of railings/Slab/approach for Bridges	-
Description of observation of CD works :		
No provision under the scheme.		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer: Ram Prabesh Saw

Designation: T.A RWD
Works Circle Siwan

PL
25.6.21
(Signature)