

कार्यपालक अभियंता, ग्रामीण कार्य विभाग कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक 502 अ.सु.

दलसिंहसराय/दिनांक 10/03/2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
सचिव-सह-प्राधिकृत पदाधिकारी
ग्रामीण पथ विकास एजेंसी पटना ।

विषय-

New Maintenance Policy 2018(MR New) योजनान्तर्गत पथ में आवंटन
उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि **New Maintenance Policy 2018(MR New)** योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान **Rs.-122.36897 (One Crore Twenty Two Lakh Thirty Six Thousand Eight Hundred Ninety Seven Rupess)** कि आवश्यकता है अधियाचना का निर्माण कार्य विशिष्टों के अनुरूप है तथा कार्य संतोषप्रद है।

अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन **Rs.-122.36897 (One Crore Twenty Two Lakh Thirty Six Thousand Eight Hundred Ninety Seven Rupess)** उपलब्ध कराने की कृपा की जाये।

- अनु0- 1) अधियाचना प्रपत्र।
2) 19 ए फॉर्म।
3) IRI Report की छायाप्रति सलग्न।
4) मापिपुस्त की छायाप्रति सलग्न।

विश्वासभाजन

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय

10/03/21

Rural Works Department, Works Division Dalsinghsarai
Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018
(Initial Rectification and Surface Renewal)

Name of Division : PIU(Dalsinghsarai)

Name of Division : PUU(Dalsinghsarai)																		
Sl. No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (in Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (in lac)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
RRM/SA/DAL/19/0014																		
1		Repair of Road Panshalla Chowk se NH 103 Halai Tak	10105093	2200 / 08.07.2019	4.520	203.00620	133.27298	35.77425	04 MBD/2020-21 24.06.20	19.11.2020	-	3836	25mm	5.10%	0.00000	0.00000	68.72917	
2		Repair of Road Maricha Chowk Se Sarjit Rai Mukhiya ke Ghar Tak	10105094		2.210	90.12970	57.05766	17.97769		19.11.2020	-	3687	25mm	5.10%	0.00000	0.00000	34.12467	
3		Repair of Road Amritpur Chowk Se Sogar Mahadalit Basti Tak	10105098		3.017	101.59590	60.50376	23.85176		19.11.2020	-	3829	25mm	5.10%	29.04180	29.04180	19.51513	
					9.747	394.73180	250.834	77.604							29.04180	29.04180	122.36897	

1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.

2 Up-to date Physical Progress has been uploaded in MIS.

[Signature]
 Sr. Divisional Account Officer
 Rural Works Department,
 Works Division Dalsinghsarai

[Signature]
 Executive Engineer
 Rural Works Department,
 Works Division Dalsinghsarai

FORM GFR-19-A

(See Govt. of India's decision(i) below rule 150)
Form of Utilisation Certificate upto March 2021

New Maintenance Policy 2018(MR New)

PIU;- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	914.98615	914.98615	Certified that out of Rs-914.98615 Lakh received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-908.42395 Lakh has been utilized for the New Maintenance Policy 2018(MR New) Scheme as given in the margin for which it was Sanctioned and that the Balance of Rs-6.56220 Lakh remaining unutilized at the end of period under the time of completion
		914.98615	914.98615	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was

Kind of Checks Exercised:-

- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurements have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have observed


3. Physical Progress Achieved

- (i) Construction of Road Works
- (ii) Construction of CD Works



Sr.DAO


Rural Works Department,
Works Division Dalsinghsarai



Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

10/03/21

File : C:\MyMaster\Bump February DSS\05021412.Xls. Section No. : 53. Eqn : $Y = 0 * X^2 + 1.136 * X + 132.5$
 Name of Customer : Chakradhar Choudhary. Name of Work Road : Repair of Road Panshulla Chowk se NH 103



Chand
 8/2/21
 J.E.

Chand
 8/2/21
 J.E.

Date	Time	Section	No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event	Y = 0 * X^2 + 1.136 * X + 132.5 X = 7000 Y = 8084 (R) RURAL ROAD Good Average Poor <4000 4001-5000 >5001		
5/2/21	13:14:3		53	0.1	380	0	3200	3600	G	25.723603	85.624393	Y = 0 * X^2 + 1.136 * X + 132.5 Curve			
5/2/21	13:14:3		53	0.1	440	20.2	3400	3800	G	25.724438	85.62409	Normal			
5/2/21	13:14:39		53	0.1	490	10.1	3600	3900	G	25.72527	85.623787	Normal			
5/2/21	13:15:0		53	0.1	360	20.2	3200	3400	G	25.725698	85.622945	Normal			
5/2/21	13:15:14		53	0.1	380	10.1	3200	3600	G	25.726293	85.622457	Normal			
5/2/21	13:16:0		53	0.1	450	10.1	3200	3400	G	25.726645	85.62335	Normal			
5/2/21	13:16:24		53	0.1	580	10.1	3600	3900	G	25.72668	85.62436	Normal			
5/2/21	13:17:0		53	0.1	490	10.1	3400	3800	G	25.726947	85.625268	Normal			
5/2/21	13:17:35		53	0.1	460	10.1	3200	3500	G	25.727427	85.62611	Normal			
5/2/21	13:18:0		53	0.1	650	10.1	3600	3900	G	25.728038	85.62668	Normal			
5/2/21	13:18:10		53	0.1	480	10.1	3600	3900	G	25.728905	85.626935	Normal			
5/2/21	13:18:46		53	0.1	460	10.1	3100	3400	G	25.729568	85.627642	Curve			
5/2/21	13:19:0		53	0.1	330	20.2	3300	3881	G	25.73038	85.627878	Normal			
5/2/21	13:19:20		53	0.1	390	20.2	3900	4200	A	25.731207	85.628332	Normal			
5/2/21	13:25:0		53	0.1	430	0	3200	3600	G	25.731747	85.629123	Speed Breaker			
5/2/21	13:25:13		53	0.1	400	20.2	3800	4300	G	25.73103	85.620555	Normal			
5/2/21	13:25:13		53	0.1	500	10.1	3600	3900	G	25.730487	85.62116	Speed Breaker			
5/2/21	13:26:0		53	0.1	540	10.1	3700	4100	A	25.729643	85.620757	Normal			
5/2/21	13:26:23		53	0.1	480	10.1	3600	3900	G	25.728778	85.620437	Speed Breaker			
5/2/21	13:26:23		53	0.1	350	20.2	3500	3800	G	25.728093	85.620757	Curve			
5/2/21	13:26:23		53	0.1	410	20.2	3400	3700	G	25.7275	85.621212	Normal			
5/2/21	13:29:20		53	0.1	400	0	3200	3600	G	25.726787	85.62175	Normal			
5/2/21	13:29:55		53	0.1	520	10.1	3500	3800	G	25.728138	85.620622	Normal			
5/2/21	13:30:0		53	0.1	580	10.1	3800	4100	A	25.727627	85.61978	Normal			
5/2/21	13:30:30		53	0.1	600	10.1	3600	3900	G	25.727032	85.619107	Speed Breaker			
5/2/21	13:31:5		53	0.1	790	10.1	3600	3800	G	25.72635	85.61847	Speed Breaker			
5/2/21	13:31:5		53	0.1	320	30.3	3200	3767	G	25.725982	85.617693	Normal			
5/2/21	13:31:41		53	0.1	450	20.2	3600	3900	G	25.725212	85.617153	Normal			
5/2/21	13:32:0		53	0.1	490	10.1	3400	3800	G	25.72473	85.616295	Normal			
5/2/21	13:32:16		53	0.1	440	10.1	3900	4200	A	25.724582	85.615487	Normal			
5/2/21	13:33:0		53	0.1	610	10.1	3800	4200	A	25.723418	85.615285	Speed Breaker			
5/2/21	13:33:27		53	0.1	650	10.1	3900	4100	A	25.722618	85.615	Curve			
5/2/21	13:35:12		53	0.1	700	0	3600	3900	G	25.72176	85.614697	Speed Breaker			
5/2/21	13:35:12		53	0.1	700	0	3600	3900	G	25.72093	85.614325	Normal			

8 June 2021
J.E.

Schedule XLV-Form No. 134

ਪੰਜਾਬੀ ਚੌਕ ਸੇ NH103. ਟੋਲੀ ਨੰਬਰ /
ਸੇ ਭੁਵਨੇਸ਼ਵਰ ਜ਼ਿਲ੍ਹਾ (ਮਿ.)

RWD, ਗੁਰਮੁਖੀ ਟੋਲੀ
DIVISION

ਮੋਰਾ
SUB-DIVISION

ਸੰਭਾਲ - ਟੋਲੀ ਟੋਲੀ

MEASUREMENT BOOK

Name of work—

1

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1st on A/c Bill					

Name of work—Palshalla

Rhowk to ~~Senger Mahadati~~

NH 103 Halaijak.

Authority—E.E. RWD.

Dalsingh sarai.

Agency—Chakradhar

Chaudhary.

Vill + P.O.—Keota,

P. S — Dalsingh sarai

Dist — Samastipur

Pin — 848114.

Date of start—20/2/2020.

Date of comp—19/11/2020.

Agg. no—04/MBD/2020-2021

— Work done —

Record Measurement—

① Clearing & grubbing
of road Land—

$$2 \times 150 \times 30 \text{m} \times 1.00 = 9000 \text{m}^2$$

$$2 \times 23 \text{m} \times 1.00 = 46 \text{m}^2$$

$$= 9046 \text{m}^2$$

Say—0.9046 hae.

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
B.F. Amount					= 3431975 = ∞
$\frac{10}{9}$ P/V & laying SDBC concrete —					
Qty vide P.No.-(8) of TMB.					
258.49 m ³					@ 9639.40
					= 2491689 = ∞
$\frac{11}{2}$ Const. of subgrade and earthen shoulder —					
Qty vide P.No.-(8) of TMB.					
1899.66 m ³					@ 176.75
					= 335765 = ∞

$\frac{12}{12}$ P/V & Laying of hot applied thermoplastic compound for road marking on bituminous surface —					
Qty vide P.No.-(9) of TMB.					
678 m ²					@ 735.40
					= 498601 = ∞
					= 6758030 = ∞
Add 12% GST					= (+) 810964 = ∞
Add 1% L.Cess					= (+) 67580 = ∞
					= 7636574 = ∞
Less 10% Below					= (-) 763657 = ∞
Grand					= 6872917 = ∞

28/12/2020
T.E.

Continuation