

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1

Email ID:-ee.rwd.sasaram1@gmail.com

Mob:- 8986915310

पत्रांक.....551 315 सासाराम/दिनांक.....13/03/2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

सेवामें,

नोडल पदाधिकारी (MR 3054)
ग्रामीणकार्यविभाग
पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाषय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु० :- यथोक्त।

विष्वासभाजन

13/3/21
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1
13/03/21

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)
Form of Utilization Certificate up to March 2021

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lacs Rs.)	Amount Received (In lacs Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA Letter No.82, dt. 13.11.2020 Letter No.84, dt. 26.11.2020 Letter No.86, dt. 11.12.2020 Letter No.05, dt. 12.01.2021 Letter No.17, dt. 26.02.2021	24012800.00 19457900.00 65864300.00 142175100.00 17,09,10,570.00	Certified that out of Rs. 42,24,20,670.00 lakh of grants-in-aid sanctioned during the years 2020-21 Infavor of EE,RWD works division Sasaram-1 a sum of Rs 25,39,65,337.00 lakh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 16,84,55,333.00 lakh remaining unutilized at the end of the period under report.
	Total:		25,15,10,100.00	


2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.


Kind of Checks exercised:-

- i. Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v. All other caudal formalities have been observed.

3. Physical Progress achieved:-

- i. Construction of Road Works.
- ii. Construction of CD works.


Divisional Accounts Officer
R.W.D. works Division
Sasaram-1


Executive Engineer
R.W.D. works Division
Sasaram-1
13/03/21

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SASARAM-1

Requisition Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- Sasaram-1

Sl no.	Package No MR-N/ 2019-20	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No& Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	3	Ara Sasaram Path se Tetari	10109022	2159 06.07.2019	1.000	48.07600	33.797	9.40848	68/MBD/ 2020-21 24.02.20	23.11.2020	-	3115	25.00	5.05	16.89850	16.89850	16.89850	
Total					1.000	48.07600	33.797	9.40848							16.89850	16.89850	16.89850	

[Signature]
S. Divisional Accounts Office
Rural Works Department, 1710314
Works Division, Sasaram-1

[Signature]
Executive Engineer
Rural Works Department
Works Division, Sasaram-1
1710314

Name of Road : Ara Sasaram Path se Tetari

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGO RY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
11/2/21	13:7:6	51	0.1	290	0	2900	3315	G	24.974313	84.19477	Normal
11/2/21	13:7:42	51	0.1	210	20.2	2100	2515	G	24.975155	84.1978	Normal
11/2/21	13:8:30	51	0.1	270	20.2	2000	2615	G	24.97587	84.20387	Normal
11/2/21	13:8:19	51	0.1	240	20.2	2400	2815	G	24.976757	84.20555	Normal
11/2/21	13:9:0	51	0.1	180	10.1	1800	2215	G	24.97668	84.22862	Normal
11/2/21	13:9:30	51	0.1	230	0	2300	2715	G	24.97637	84.23635	Normal
11/2/21	13:10:5	51	0.1	180	10.1	1800	2215	G	24.976108	84.24662	Normal
11/2/21	13:11:50	51	0.1	250	0	2500	2915	G	24.976177	84.24308	Normal
11/2/21	13:12:0	51	0.1	250	10.1	2500	2915	G	24.976488	84.2337	Normal
11/2/21	13:12:25	51	0.1	220	363.6	2700	3115	G	24.976712	84.22255	Normal
Total			1.00								

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2700$$

$$Y = 3115$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

13/3/21
 Secretary
 A.V.D.(M) Dr. Secretary

Test Date :	11/2 /2021 ▾	Road Name :	Ara Sasaram Path se Tehari
Machine No :	391	Road Type :	(R) RURAL ROAD ▾
Start S No :	7937	Side :	Sasaram
Start E No :	7950	Interval	
Weather :	Normal	U/V Range :	1015 To 4000 1000 mm/Km
Start Location :	24.97431,84.116	Dist Range :	0 To 0.42 0.028 = 1000 m
End Location :	24.97671,84.22	Equation :	$Y = 0 * X^2 + 1.000 * X + 415.2$


Print

Generate Report and Graph

Redraw Graph

Map View

File 1: Bump Rag and Report Request Nov 202024, Sushma and Narendra KA11021335 Graph. Xs. Section No. Name of Customer :Narendra Kumar, Name of Work/ Road :Ara Sasaram Path se Telari, Lab Job number :51



Mr

W.
W. D. (W) Div. Bureau