## **TECHNICAL REPORT**

Name of Work	– FDR To Road From
--------------	--------------------

Head - FDF

Estimated cost - 4.8/29.1... Lacs

The work done estimate has been framed for the restoration (motarable) of traffic for the above road which was damage during the year 2020-2021 flash flood.

## (A) Source of materials

Brick Bats - Local Kiln

Fine sand - Local

Cement Bag - Local Market

Aggregate for G.S.B - Matigara (Silliguri) by road up to site.

Bamboo - Local

Earth - Private land from 1000m lead.

(B) <u>Rate</u> - Carriage has been analyzed on minimum lead. Finished rate has been calculated without contractor's profit on MORD norms. Carriage of materials has been added to finished rate. Basic Rates are evaluated from rates approved by State schedule rate committee. 12% GST& 1% Labour cess has been added in the estimate in abstract part.

Sanction of estimate is much needed for payment of the work which was

already done.

J.E

R.W.D

Kishanganj-1

A.E

R.W.D

Kishanganj-1

FE

R.W.D

Kishanganj-1

Inspection Report for flood damage work

1. Name of PIUs- Executive Eng. RWD works division, Kishingon, -1.

2. Name of Block/Road- Terhagachh LOAA Kajleta road to Kuweri A. For Road Kajleta, 1st cutting.

1.5

1.Damage Location/Chainage: 0 · 00 km.
2. Damage Lengh : 40m.

3. Nature of Damage : washed out fronk demage.

4. Details of Restoration

i Material being used in Restoration : Lo cal search, Brick bets-

ii Equipment/Tools being used in Restoration works: Tracter:
iii Procedure taken up in Restoration works: resmust.

iv Restored Length

B. For Bridge

Date:

1.Damage Location/Chainage:

2. Damage Lengh : 3.Nature of Damage :

4.Details of Restoration

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

12/2/202

Signature of JEAE/EE

Signature

(Name of Inspector)

## Inspection Report for flood damage work Date: 1. Name of PIUs- Executive Eng. RWD works division, Hickoryeng-1. 2. Name of Block/Road- Teshagachh Lo44 Kaileta soud to Kueri Kaileta, 2nd cutting. 1.Damage Location/Chainage: 0.300 km : your flank demage. 2. Damage Lengh 3. Nature of Damage : Botch bots, Local send bags. 4. Details of Restoration i Material being used in Restoration ii Equipment Tools being used in Restoration works: Trooter. iii Procedure taken up in Restoration works iv Restored Length B. For Bridge 1.Damage Location/Chainage: 2. Damage Lengh: N · A · 3. Nature of Damage 4. Details of Restoration i Material being used in Restoration ii Equipment/Tools being used in Restoration works: iii Procedure taken up in Restoration works iv Restored Length

Signature of JE/AF/EE

(Name of Inspector)

Scanned by CamScanner

## **Abstract of Cost**

ae of Work:-

L044 Kajleta road to Kuwari Kajleta

Block :-

Terhagachh

District:-

Kishanganj

S.L No.	Name of cutting of roads	Chainage in Km	Length in metre	Amount (In Rs.)	
1	L044 Kajleta road to Kuwari Kajleta 1st Cutting	0.00	40.00	Rs 1 <b>70</b> 812.00	
2	L044 Kajleta road to Kuwari Kajleta 2nd Cutting	0.30	90.00	Rs 310479.00	
	Total Cost=		4,81,291 = 0 Rs 418291.00	ω.	

25/13/20 -

RWD Terhagachh A.E. 112/20

R.W.D Terhagachh E.E \$5/12

R.W.D Kishanganj - I

Technically approved for ₹. 4.84291= 00

(RS. Four Lacs eight annousand and two hundred

minety-one only.

Scanned with CamScanner