

1
Name of work—
Situation of work—
Agency by which work is executed—
Date of measurement—
No. and date of agreement.
(These four lines should be repeated at the commencement of
the measurements relating to each work.)

(1) ~~Cost~~ Profit Max. cost max
sign based ~~do do all~~
Comp jobs
- 2 No.

(2) Const of reference and
working benchmark ~~do do~~
all comp jobs
 $17 \times 30 = 510 \text{ m}$
 $= 0.51 \text{ km}$

(3) Const of reference pills
~~do do all comp jobs~~
 $17 \times 30 = 510 \text{ m}$
 $= 0.51 \text{ km}$

Scanned with CamScanner

Continuation